

IntelliSens[®]

The smarter sensor

Programmable Multi-Application Sensors

- Cover multiple vehicles with one original equipment equivalent sensor
- Programs in 3 seconds for quick and easy service
- Re-programmable as well as copy/clone functionality ideal for winter tire change-over
- Clamp-in valve is adjustable up to 36 degrees
- WAL (wireless auto locate) for quick and easy tire rotations
- Supported by Bartec, ATEQ, Snap-on, NAPA, Bosch and Corgi TPMS diagnostic tools
- Advanced software within the sensor transmits temperature and rapid pressure loss
- Three year warranty

| Order No. | Mfr. No. | Description | Freq. | Valve Type |
|-----------|----------|------------------|---------|------------|
| 23719 | UVS4010 | Universal Sensor | 433 MHz | Clamp-in |
| 23720 | UVS2000 | Universal Sensor | 433 MHz | Clamp-in |
| 23738 | UVS3010 | Universal Sensor | 315 MHz | Clamp-in |
| 23721 | UVS1000 | Universal Sensor | 315 MHz | Clamp-in |
| 23739 | UVS4011 | Universal Sensor | 433 MHz | Snap-in |
| 23722 | UVS3011 | Universal Sensor | 315 MHz | Snap-in |

Additional Clamp-In Valve Options

| Order No. | Mfr. No. | Valve Length | Valve Color |
|-----------|----------|--------------|-------------|
| 23740 | RDV026 | 43mm | Black |
| 23741 | RDV027 | 43mm | Grey |



23740



23741



23721
23738

23722
23739

HUF Original Equipment Sensors

- Match OE sensors in function and design
- The only original equipment sensor available for high-end European vehicles
- No programming required
- Quick installation with only a relearn process needed
- Sensors are shipped in sleep-mode to extend battery life
- WAL (wireless auto locate) for quick and easy tire rotations



| Order No. | Mfr. No. | Freq. | Valve Type |
|-----------|-----------|--------|------------|
| 23700 | RDE001V21 | 433MHz | Clamp-in |
| 23701 | RDE002V21 | 433MHz | Clamp-in |
| 23702 | RDE003V21 | 433MHz | Clamp-in |
| 23703 | RDE004V21 | 315MHz | Clamp-in |
| 23704 | RDE005V21 | 433MHz | Clamp-in |
| 23705 | RDE008V21 | 433MHz | Clamp-in |
| 23706 | RDE009 | 433MHz | No Valve |

| Order No. | Mfr. No. | Freq. | Valve Type |
|-----------|-----------|--------|------------|
| 23707 | RDE011V21 | 433MHz | Clamp-in |
| 23708 | RDE012V21 | 433MHz | Clamp-in |
| 23709 | RDE013V21 | 433MHz | Clamp-in |
| 23710 | RDE014V21 | 315MHz | Clamp-in |
| 23711 | RDE015V21 | 315MHz | Clamp-in |
| 23712 | RDE016V21 | 315MHz | Clamp-in |
| 23713 | RDE017V21 | 433MHz | Clamp-in |

| Order No. | Mfr. No. | Freq. | Valve Type |
|-----------|-----------|--------|------------|
| 23714 | RDE018V21 | 433MHz | Clamp-in |
| 23715 | RDE019V21 | 315MHz | Clamp-in |
| 23716 | RDE020V21 | 315MHz | Clamp-in |
| 23717 | RDE021 | 433MHz | No Valve |
| 23718 | RDE022V21 | 315MHz | Clamp-in |
| 23736 | RDE023V41 | 315MHz | Snap-in |
| 23737 | RDE027V21 | 433MHz | Clamp-in |

GEN2 HUF TPMS Valve Kits

- Formerly Beru



Includes stem, nut, screw and plastic valve cap.

| Order No. | Mfr. No. | Color Code | Valve Length |
|-----------|----------|------------|--------------|
| 23731 | RDV021 | Silver | 43mm |
| 23732 | RDV022 | Green | 48mm |
| 23733 | RDV023 | Black | 49mm |
| 23734 | RDV024 | Orange | 51mm |
| 23735 | RDV025 | Yellow | 56mm |

To Order
800-998-9897
myerstiresupply.com

Table of Contents

| | |
|--|-------|
| Applications Listings | 3-12 |
| OE Replacement Sensors | 13-17 |
| Huf Intellisens Universal Sensors | 18-19 |
| Valves | 20 |
| OE Interchange | 21-22 |



Huf Warranty: All products sold are warranted against defects in workmanship and material under normal use and service for the earlier of (1) a period of three years from the date of installation, or (2) a period of five years from the date of sale to the Huf Distributor. Huf will either repair or replace any product which fails during this period. This warranty does not include any labor for the repair or replacement of the product.

Application Listings

| Make/Model | Year | IntelliSens Universal | OE Replacement | Frequency |
|---------------------|-----------|-----------------------|----------------|-----------|
| Acura | | | | |
| CSX | 2008-2011 | UVS3010/UVS3011 | | 315 MHz |
| ILX | 2013-2015 | UVS3010/UVS3011 | | 315 MHz |
| Aston Martin | | | | |
| DB9 | 2010-2015 | UVS2000 | RDE011V21 | 433 MHz |
| DB9 | 2010-2015 | | RDE022V21 | 315 MHz |
| DBS | 2008-2012 | UVS2000 | RDE011V21 | 433 MHz |
| DBS | 2008-2012 | | RDE022V21 | 315 MHz |
| Rapide | 2010-2011 | UVS2000 | RDE011V21 | 433 MHz |
| Rapide | 2010-2011 | | RDE022V21 | 315 MHz |
| V12 Vantage | 2013-2015 | UVS2000 | RDE011V21 | 433 MHz |
| V12 Vantage | 2013-2015 | | RDE022V21 | 315 MHz |
| V8 Vantage | 2010-2015 | UVS2000 | RDE011V21 | 433 MHz |
| V8 Vantage | 2010-2015 | | RDE022V21 | 315 MHz |
| Vanquish | 2012-2015 | | RDE022V21 | 315 MHz |
| Vanquish | 2013-2015 | UVS2000 | RDE011V21 | 433 MHz |
| Virage | 2012 | UVS2000 | RDE011V21 | 433 MHz |
| Audi | | | | |
| A3 | 2006-2009 | UVS3010/UVS3011 | | 315 MHz |
| A4 | 2009 | UVS3010/UVS3011 | | 315 MHz |
| A4 | 2002-2008 | UVS2000 | RDE011V21 | 433 MHz |
| A5 | 2008-2009 | UVS3010/UVS3011 | | 315 MHz |
| A6 | 2004 | UVS2000 | RDE011V21 | 433 MHz |
| A6 | 2005 | | RDE001V21 | 433 MHz |
| A6 | 2005 | UVS2000 | RDE011V21 | 433 MHz |
| A6 | 2000-2003 | | RDE001V21 | 433 MHz |
| A6 | 2000-2004 | | RDE004V21 | 315 MHz |
| A6 | 2005-2008 | | RDE022V21 | 315 MHz |
| A6 | 2006-2009 | UVS2000 | RDE011V21 | 433 MHz |
| A8 | 2000-2009 | | RDE001V21 | 433 MHz |
| A8 | 2000-2009 | | RDE004V21 | 315 MHz |
| Allroad Quattro | 2001-2005 | | RDE001V21 | 433 MHz |
| Allroad Quattro | 2001-2005 | | RDE004V21 | 315 MHz |
| Q7 | 2005-2009 | UVS2000 | RDE011V21 | 433 MHz |
| R8 | 2008-2015 | UVS2000 | RDE011V21 | 433 MHz |
| RS4 | 2007-2009 | UVS2000 | RDE011V21 | 433 MHz |
| RS6 | 2003 | | RDE001V21 | 433 MHz |
| RS6 | 2003 | | RDE004V21 | 315 MHz |
| RS7 | 2014-2015 | UVS2000 | RDE011V21 | 433 MHz |
| S4 | 2002-2009 | UVS2000 | RDE011V21 | 433 MHz |
| S4 | 2005-2007 | | RDE022V21 | 315 MHz |
| S5 | 2008-2009 | UVS3010/UVS3011 | | 315 MHz |
| S6 | 2004-2009 | UVS2000 | RDE011V21 | 433 MHz |
| S6 | 2004-2008 | | RDE022V21 | 315 MHz |
| S8 | 1999-2009 | | RDE001V21 | 433 MHz |
| S8 | 1999-2009 | | RDE004V21 | 315 MHz |
| TT | 2006-2009 | UVS3010/UVS3011 | | 315 MHz |
| Bentley | | | | |
| Arnage | 2008-2009 | UVS2000 | RDE011V21 | 433 MHz |
| Azure | 2007-2009 | UVS2000 | RDE011V21 | 433 MHz |
| Brooklands | 2008-2011 | UVS2000 | RDE011V21 | 433 MHz |
| Continental | 2003-2005 | | RDE001V21 | 433 MHz |
| Continental | 2005-2015 | UVS2000 | RDE011V21 | 433 MHz |
| Flying Spur | 2006-2015 | UVS2000 | RDE011V21 | 433 MHz |
| Mulsanne | 2011-2016 | UVS2000 | RDE011V21 | 433 MHz |
| BMW | | | | |
| 128i | 2008-2010 | UVS2000 | RDE008V21 | 433 MHz |
| 128i | 2010-2013 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| 135i | 2008-2010 | UVS2000 | RDE008V21 | 433 MHz |

| Make/Model | Year | IntelliSens Universal | OE Replacement | Frequency |
|------------|-----------|-----------------------|----------------|-----------|
| 135i | 2010-2013 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| 135is | 2013 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| 228i | 2014-2015 | UVS4010/UVS4011 | RDE027V21 | 433 MHz |
| 320i | 2013-2014 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| 320i | 2014-2015 | UVS4010/UVS4011 | RDE027V21 | 433 MHz |
| 323Ci | 2000 | | RDE004V21 | 315 MHz |
| 323Ci | 2000 | | RDE002V21 | 433 MHz |
| 323i | 1999-2000 | | RDE004V21 | 315 MHz |
| 323i | 1999-2000 | | RDE002V21 | 433 MHz |
| 323is | 1999 | | RDE004V21 | 315 MHz |
| 323is | 1999 | | RDE002V21 | 433 MHz |
| 325Ci | 2001-2005 | | RDE004V21 | 315 MHz |
| 325Ci | 2001-2006 | | RDE002V21 | 433 MHz |
| 325i | 2001-2005 | | RDE004V21 | 315 MHz |
| 325i | 2001-2006 | | RDE002V21 | 433 MHz |
| 325xi | 2001-2005 | | RDE004V21 | 315 MHz |
| 325xi | 2001-2006 | | RDE002V21 | 433 MHz |
| 328Ci | 2000 | | RDE004V21 | 315 MHz |
| 328Ci | 2000 | | RDE002V21 | 433 MHz |
| 328d | 2014 | | RDE017V21 | 433 MHz |
| 328d | 2014-2015 | UVS4010/UVS4011 | RDE027V21 | 433 MHz |
| 328i | 2012 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| 328i | 1999-2000 | UVS4010/UVS4011 | RDE004V21 | 315 MHz |
| 328i | 1999-2000 | | RDE002V21 | 433 MHz |
| 328i | 2007-2009 | UVS2000 | RDE008V21 | 433 MHz |
| 328i | 2010-2012 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| 328i | 2013-2014 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| 328i | 2014-2015 | UVS4010/UVS4011 | RDE027V21 | 433 MHz |
| 328is | 1999 | | RDE004V21 | 315 MHz |
| 328is | 1999 | | RDE002V21 | 433 MHz |
| 328xi | 2007-2008 | UVS2000 | RDE008V21 | 433 MHz |
| 330Ci | 2001-2005 | | RDE004V21 | 315 MHz |
| 330Ci | 2001-2006 | | RDE002V21 | 433 MHz |
| 330i | 2001-2004 | | RDE004V21 | 315 MHz |
| 330i | 2001-2004 | | RDE002V21 | 433 MHz |
| 330xi | 2001-2005 | | RDE004V21 | 315 MHz |
| 330xi | 2001-2006 | | RDE002V21 | 433 MHz |
| 335d | 2009 | UVS2000 | RDE008V21 | 433 MHz |
| 335d | 2012 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| 335d | 2009-2012 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| 335i | 2012 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| 335i | 2007-2009 | UVS2000 | RDE008V21 | 433 MHz |
| 335i | 2009-2012 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| 335i | 2013-2014 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| 335i | 2014-2015 | UVS4010/UVS4011 | RDE027V21 | 433 MHz |
| 335is | 2012 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| 335is | 2013 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| 335is | 2011-2012 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| 335xi | 2007-2008 | UVS2000 | RDE008V21 | 433 MHz |
| 428i | 2014 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| 428i | 2014-2015 | UVS4010/UVS4011 | RDE027V21 | 433 MHz |
| 435i | 2014 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| 435i | 2014-2015 | UVS4010/UVS4011 | RDE027V21 | 433 MHz |
| 525i | 2001-2002 | | RDE004V21 | 315 MHz |
| 525i | 2005-2005 | | RDE002V21 | 433 MHz |
| 525i | 2006-2007 | UVS2000 | RDE008V21 | 433 MHz |
| 525xi | 2006-2007 | UVS2000 | RDE008V21 | 433 MHz |
| 528i | 2014 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| 528i | 1997-2000 | | RDE004V21 | 315 MHz |

Application Listings

| Make/Model | Year | IntelliSens Universal | OE Replacement | Frequency |
|----------------|-----------|-----------------------|----------------|-----------|
| 528i | 2008-2010 | UVS2000 | RDE008V21 | 433 MHz |
| 528i | 2010-2013 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| 528i | 2014-2015 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| 528xi | 2008 | UVS2000 | RDE008V21 | 433 MHz |
| 530i | 2001-2002 | | RDE004V21 | 315 MHz |
| 530i | 2002-2005 | | RDE002V21 | 433 MHz |
| 530i | 2006-2007 | UVS2000 | RDE008V21 | 433 MHz |
| 530xi | 2006-2007 | UVS2000 | RDE008V21 | 433 MHz |
| 535d | 2014 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| 535d | 2014-2015 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| 535i | 2014 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| 535i | 2008-2010 | UVS2000 | RDE008V21 | 433 MHz |
| 535i | 2010-2013 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| 535i | 2014-2015 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| 535xi | 2008 | UVS2000 | RDE008V21 | 433 MHz |
| 540i | 1997-2002 | | RDE004V21 | 315 MHz |
| 540i | 2002-2003 | | RDE002V21 | 433 MHz |
| 545i | 2004-2005 | | RDE002V21 | 433 MHz |
| 550i | 2014 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| 550i | 2006-2010 | UVS2000 | RDE008V21 | 433 MHz |
| 550i | 2010-2013 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| 550i | 2014-2015 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| 640i | 2012-2014 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| 640i | 2014-2015 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| 650i | 2006-2010 | UVS2000 | RDE008V21 | 433 MHz |
| 650i | 2012-2014 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| 650i | 2014-2016 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| 740i | 1997-2001 | | RDE004V21 | 315 MHz |
| 740i | 1998-2001 | | RDE002V21 | 433 MHz |
| 740i | 2011-2014 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| 740i | 2014-2015 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| 740iL | 1997-2001 | | RDE004V21 | 315 MHz |
| 740iL | 1998-2001 | | RDE004V21 | 315 MHz |
| 740Ld | 2015 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| 740Li | 2011-2014 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| 740Li | 2014-2015 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| 745i | 2002 | | RDE004V21 | 315 MHz |
| 745i | 2002-2005 | | RDE002V21 | 433 MHz |
| 745Li | 2002 | | RDE004V21 | 315 MHz |
| 745Li | 2005-2005 | | RDE002V21 | 433 MHz |
| 750i | 2014 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| 750i | 2006-2010 | UVS2000 | RDE008V21 | 433 MHz |
| 750i | 2010-2013 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| 750i | 2014-2015 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| 750iL | 1997-2001 | | RDE004V21 | 315 MHz |
| 750iL | 1998-2001 | | RDE004V21 | 315 MHz |
| 750Li | 2014 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| 750Li | 2006-2010 | UVS2000 | RDE008V21 | 433 MHz |
| 750Li | 2010-2013 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| 750Li | 2014-2015 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| 760i | 2006 | UVS2000 | RDE008V21 | 433 MHz |
| 760i | 2004-2005 | | RDE002V21 | 433 MHz |
| 760Li | 2014 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| 760Li | 2003-2005 | | RDE002V21 | 433 MHz |
| 760Li | 2006-2010 | UVS2000 | RDE008V21 | 433 MHz |
| 760Li | 2010-2013 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| 760Li | 2014-2015 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| ActiveHybrid 3 | 2013-2014 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| ActiveHybrid 3 | 2014-2015 | UVS4010/UVS4011 | RDE027V21 | 433 MHz |

| Make/Model | Year | IntelliSens Universal | OE Replacement | Frequency |
|-----------------------------|-----------|-----------------------|----------------|-----------|
| ActiveHybrid 5 | 2014 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| ActiveHybrid 5 | 2013-2014 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| ActiveHybrid 7 | 2014 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| ActiveHybrid 7 | 2013-2014 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| Alpina B6 xDrive Gran Coupe | 2015 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| Alpina B7 | 2011 | | RDE002V21 | 433 MHz |
| Alpina B7 | 2014 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| Alpina B7 | 2007-2008 | UVS2000 | RDE008V21 | 433 MHz |
| Alpina B7 | 2012-2014 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| i3 | 2014-2015 | UVS4010/UVS4011 | RDE027V21 | 433 MHz |
| i8 | 2015 | UVS4010/UVS4011 | RDE027V21 | 433 MHz |
| M235i | 2014-2015 | UVS4010/UVS4011 | RDE027V21 | 433 MHz |
| M3 | 2001 | | RDE004V21 | 315 MHz |
| M3 | 2015 | UVS4010/UVS4011 | RDE027V21 | 433 MHz |
| M3 | 2002-2003 | | RDE002V21 | 433 MHz |
| M3 | 2004-2009 | UVS2000 | RDE008V21 | 433 MHz |
| M3 | 2009-2013 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| M4 | 2015 | UVS4010/UVS4011 | RDE027V21 | 433 MHz |
| M5 | 2014 | | RDE012V21 | 433 MHz |
| M5 | 2000-2003 | | RDE004V21 | 315 MHz |
| M5 | 2000-2003 | UVS4010/UVS4011 | RDE002V21 | 433 MHz |
| M5 | 2006-2010 | UVS2000 | RDE008V21 | 433 MHz |
| M5 | 2010-2013 | | RDE012V21 | 433 MHz |
| M5 | 2014-2015 | | RDE017V21 | 433 MHz |
| M6 | 2006-2010 | UVS2000 | RDE008V21 | 433 MHz |
| M6 | 2012-2014 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| M6 | 2014-2016 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| X1 | 2013-2014 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| X1 | 2014-2015 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| X3 | 2006-2010 | UVS2000 | RDE008V21 | 433 MHz |
| X3 | 2010-2014 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| X3 | 2014-2016 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| X4 | 2015-2016 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| X5 | 2000-2004 | | RDE003V21 | 433 MHz |
| X5 | 2005-2010 | UVS2000 | RDE008V21 | 433 MHz |
| X5 | 2010-2013 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| X5 | 2013-2015 | UVS4010/UVS4011 | RDE027V21 | 433 MHz |
| X6 | 2011 | | RDE022V21 | 315 MHz |
| X6 | 2008-2010 | UVS2000 | RDE008V21 | 433 MHz |
| X6 | 2010-2014 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| X6 | 2014-2015 | UVS4010/UVS4011 | RDE027V21 | 433 MHz |
| Z3 | 2000-2002 | | RDE004V21 | 315 MHz |
| Z4 | 2014 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| Z4 | 2003-2010 | UVS2000 | RDE008V21 | 433 MHz |
| Z4 | 2010-2013 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| Z4 | 2014-2016 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| Buick | | | | |
| Allure | 2007-2010 | UVS3010/UVS3011 | | 315 MHz |
| Enclave | 2015 | UVS3010/UVS3011 | | 315 MHz |
| Enclave | 2008-2014 | UVS3010/UVS3011 | | 315 MHz |
| Encore | 2013-2015 | UVS3010/UVS3011 | | 315 MHz |
| LaCrosse | 2006-2015 | UVS3010/UVS3011 | | 315 MHz |
| Lucerne | 2007-2011 | UVS3010/UVS3011 | | 315 MHz |
| Rainier | 2006-2007 | UVS3010/UVS3011 | | 315 MHz |
| Regal | 2011-2015 | UVS3010/UVS3011 | | 315 MHz |
| Verano | 2012-2015 | UVS3010/UVS3011 | | 315 MHz |
| Cadillac | | | | |

Application Listings

| Make/Model | Year | IntelliSens Universal | OE Replacement | Frequency |
|-------------------|-----------|-----------------------|----------------|-----------|
| ATS | 2013-2015 | UVS3010/UVS3011 | | 315 MHz |
| CTS | 2004-2015 | UVS3010/UVS3011 | | 315 MHz |
| CTS | 2014-2015 | UVS3010/UVS3011 | | 315 MHz |
| DTS | 2006-2011 | UVS3010/UVS3011 | | 315 MHz |
| ELR | 2014-2015 | UVS3010/UVS3011 | | 315 MHz |
| Escalade | 2004-2015 | UVS3010/UVS3011 | | 315 MHz |
| Escalade ESV | 2015 | UVS3010/UVS3011 | | 315 MHz |
| SRX | 2004-2015 | UVS3010/UVS3011 | | 315 MHz |
| SRX | 2007-2009 | UVS4010/UVS4011 | | 433 MHz |
| STS | 2009 | UVS4010/UVS4011 | | 433 MHz |
| STS | 2005-2011 | UVS3010/UVS3011 | | 315 MHz |
| XLR | 2004-2009 | UVS3010/UVS3011 | | 315 MHz |
| XTS | 2013-2015 | UVS3010/UVS3011 | | 315 MHz |
| Chevrolet | | | | |
| Avalanche | 2004 | UVS3010/UVS3011 | | 315 MHz |
| Avalanche | 2005-2013 | UVS3010/UVS3011 | | 315 MHz |
| Camaro | 2010-2015 | UVS3010/UVS3011 | | 315 MHz |
| Camaro | 2012-2015 | UVS3010/UVS3011 | | 315 MHz |
| Caprice | 2011-2015 | UVS3010/UVS3011 | | 315 MHz |
| Captiva Sport | 2012-2015 | UVS3010/UVS3011 | | 315 MHz |
| City Express | 2015 | UVS3010/UVS3011 | | 315 MHz |
| Cobalt | 2008-2010 | UVS3010/UVS3011 | | 315 MHz |
| Colorado | 2015 | UVS3010/UVS3011 | | 315 MHz |
| Colorado | 2007-2012 | UVS3010/UVS3011 | | 315 MHz |
| Corvette | 2005-2014 | UVS3010/UVS3011 | | 315 MHz |
| Corvette | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| Cruze | 2011-2016 | UVS3010/UVS3011 | | 315 MHz |
| Equinox | 2007-2015 | UVS3010/UVS3011 | | 315 MHz |
| Express 1500 | 2008-2014 | UVS3010/UVS3011 | | 315 MHz |
| Express 2500 | 2008-2015 | UVS3010/UVS3011 | | 315 MHz |
| Express 3500 | 2008-2015 | UVS3010/UVS3011 | | 315 MHz |
| HHR | 2008-2011 | UVS3010/UVS3011 | | 315 MHz |
| Impala | 2006-2015 | UVS3010/UVS3011 | | 315 MHz |
| Impala Limited | 2014 | UVS3010/UVS3011 | | 315 MHz |
| Malibu | 2008-2015 | UVS3010/UVS3011 | | 315 MHz |
| Monte Carlo | 2006-2007 | UVS3010/UVS3011 | | 315 MHz |
| Oriando | 2012-2015 | UVS3010/UVS3011 | | 315 MHz |
| Silverado 1500 | 2004 | UVS3010/UVS3011 | | 315 MHz |
| Silverado 1500 | 2005-2015 | UVS3010/UVS3011 | | 315 MHz |
| Silverado 2500 HD | 2004 | UVS3010/UVS3011 | | 315 MHz |
| Silverado 2500 HD | 2005-2015 | UVS3010/UVS3011 | | 315 MHz |
| Silverado 3500 HD | 2004 | UVS3010/UVS3011 | | 315 MHz |
| Silverado 3500 HD | 2005-2015 | UVS3010/UVS3011 | | 315 MHz |
| Sonic | 2012-2014 | UVS3010/UVS3011 | | 315 MHz |
| Spark | 2013-2015 | UVS3010/UVS3011 | | 315 MHz |
| SS | 2014-2015 | UVS3010/UVS3011 | | 315 MHz |
| SSR | 2006 | UVS3010/UVS3011 | | 315 MHz |
| Suburban | 2015 | UVS3010/UVS3011 | | 315 MHz |
| Suburban 1500 | 2004 | UVS3010/UVS3011 | | 315 MHz |
| Suburban 1500 | 2005-2014 | UVS3010/UVS3011 | | 315 MHz |
| Suburban 2500 | 2004 | UVS3010/UVS3011 | | 315 MHz |
| Suburban 2500 | 2005-2013 | UVS3010/UVS3011 | | 315 MHz |
| Tahoe | 2004 | UVS3010/UVS3011 | | 315 MHz |
| Tahoe | 2005-2015 | UVS3010/UVS3011 | | 315 MHz |
| Trailblazer | 2006-2009 | UVS3010/UVS3011 | | 315 MHz |

| Make/Model | Year | IntelliSens Universal | OE Replacement | Frequency |
|-----------------|-----------|-----------------------|----------------|-----------|
| Traverse | 2015 | UVS3010/UVS3011 | | 315 MHz |
| Traverse | 2009-2014 | UVS3010/UVS3011 | | 315 MHz |
| Trax | 2013-2015 | UVS3010/UVS3011 | | 315 MHz |
| Uplander | 2008 | UVS3010/UVS3011 | | 315 MHz |
| Volt | 2011-2015 | UVS3010/UVS3011 | | 315 MHz |
| Chrysler | | | | |
| 200 | 2011-2014 | UVS3010/UVS3011 | | 315 MHz |
| 300 | 2005-2007 | UVS3010/UVS3011 | | 315 MHz |
| 300 | 2006-2015 | UVS4010/UVS4011 | | 433 MHz |
| 300M | 2002-2004 | UVS4010/UVS4011 | | 433 MHz |
| Aspen | 2007-2009 | UVS3010/UVS3011 | | 315 MHz |
| Concorde | 2002-2004 | UVS4010/UVS4011 | | 433 MHz |
| Crossfire | 2004-2008 | UVS4010/UVS4011 | | 433 MHz |
| Crossfire | 2006-2008 | UVS3010/UVS3011 | | 315 MHz |
| Pacifica | 2004 | UVS3010/UVS3011 | | 315 MHz |
| Pacifica | 2004 | UVS4010/UVS4011 | | 433 MHz |
| Pacifica | 2005-2008 | UVS3010/UVS3011 | | 315 MHz |
| Prowler | 2002 | UVS4010/UVS4011 | | 433 MHz |
| PT Cruiser | 2008-2010 | UVS3010/UVS3011 | | 315 MHz |
| Sebring | 2007-2010 | UVS3010/UVS3011 | | 315 MHz |
| Sebring | 2008 | UVS4010/UVS4011 | | 433 MHz |
| Sebring | 2009 | UVS4010/UVS4011 | | 433 MHz |
| Town & Country | 2002-2003 | UVS4010/UVS4011 | | 433 MHz |
| Town & Country | 2004-2007 | UVS3010/UVS3011 | | 315 MHz |
| Town & Country | 2008-2015 | UVS4010/UVS4011 | | 433 MHz |
| Voyager | 2002-2003 | UVS4010/UVS4011 | | 433 MHz |
| Dodge | | | | |
| Avenger | 2008-2014 | UVS3010/UVS3011 | | 315 MHz |
| Caliber | 2007-2012 | UVS3010/UVS3011 | | 315 MHz |
| Caravan | 2002-2003 | UVS4010/UVS4011 | | 433 MHz |
| Caravan | 2004-2007 | UVS3010/UVS3011 | | 315 MHz |
| Challenger | 2008-2015 | UVS4010/UVS4011 | | 433 MHz |
| Charger | 2006-2007 | UVS3010/UVS3011 | | 315 MHz |
| Charger | 2008-2015 | UVS4010/UVS4011 | | 433 MHz |
| Dakota | 2011 | UVS3010/UVS3011 | | 315 MHz |
| Dakota | 2008-2010 | UVS3010/UVS3011 | | 315 MHz |
| Dakota | 2008-2010 | UVS3010/UVS3011 | | 315 MHz |
| Durango | 2007-2009 | UVS3010/UVS3011 | | 315 MHz |
| Durango | 2011-2015 | UVS4010/UVS4011 | | 433 MHz |
| Grand Caravan | 2002-2003 | UVS4010/UVS4011 | | 433 MHz |
| Grand Caravan | 2004-2007 | UVS3010/UVS3011 | | 315 MHz |
| Grand Caravan | 2008-2015 | UVS4010/UVS4011 | | 433 MHz |
| Intrepid | 2002-2004 | UVS4010/UVS4011 | | 433 MHz |
| Journey | 2009-2015 | UVS4010/UVS4011 | | 433 MHz |
| Magnum | 2008 | UVS4010/UVS4011 | | 433 MHz |
| Magnum | 2005-2007 | UVS3010/UVS3011 | | 315 MHz |
| Nitro | 2007-2011 | UVS3010/UVS3011 | | 315 MHz |
| Ram 1500 | 2008 | UVS3010/UVS3011 | | 315 MHz |
| Ram 1500 | 2009 | UVS4010/UVS4011 | | 433 MHz |
| Ram 1500 | 2009 | UVS3010/UVS3011 | | 315 MHz |
| Ram 1500 | 2010 | UVS4010/UVS4011 | | 433 MHz |
| Ram 2500 | 2008-2009 | UVS3010/UVS3011 | | 315 MHz |
| Ram 2500 | 2009-2010 | UVS4010/UVS4011 | | 433 MHz |
| Ram 3500 | 2008-2009 | UVS3010/UVS3011 | | 315 MHz |
| Ram 3500 | 2009-2010 | UVS4010/UVS4011 | | 433 MHz |
| Sprinter 2500 | 2007-2009 | UVS3010/UVS3011 | | 315 MHz |

Application Listings

| Make/Model | Year | IntelliSens Universal | OE Replacement | Frequency |
|------------------|-----------|-----------------------|-------------------------|-----------|
| Sprinter 3500 | 2007-2009 | UVS3010/UVS3011 | | 315 MHz |
| Stratus | 2007 | UVS3010/UVS3011 | | 315 MHz |
| Viper | 2003-2006 | UVS4010/UVS4011 | | 433 MHz |
| Viper | 2008-2010 | UVS4010/UVS4011 | | 433 MHz |
| Ferrari | | | | |
| 458 Italia | 2009-2013 | UVS2000 | RDE011V21 | 433 MHz |
| 550 Maranello | 2001 | | RDE001V21 | 433 MHz |
| 575 M Maranello | 2002-2005 | | RDE004V21 | 315 MHz |
| 575 M Maranello | 2002-2006 | | RDE001V21 | 433 MHz |
| 599 GTB | 2006-2012 | | RDE001V21 | 433 MHz |
| 612 Scaglietti | 2004-2011 | | RDE001V21 | 433 MHz |
| California | 2009-2014 | UVS2000 | RDE011V21 | 433 MHz |
| Enzo | 2003-2004 | | RDE005V21 | 433 MHz |
| F12 Berlinetta | 2012-2014 | UVS2000 | RDE011V21 | 433 MHz |
| F430 | 2005-2007 | | RDE001V21 | 433 MHz |
| F430 | 2007-2009 | UVS2000 | RDE011V21 | 433 MHz |
| FF | 2012-2014 | UVS2000 | RDE011V21 | 433 MHz |
| Fiat | | | | |
| 500 | 2012-2015 | UVS4010/UVS4011 | | 433 MHz |
| 500L | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| Ford | | | | |
| C-Max | 2013-2015 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| Crown Victoria | 2006-2011 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| E-150 | 2010 | UVS3010/UVS3011 | RDE015V21 | 315 MHz |
| E-150 | 2010 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| E-150 | 2007-2009 | UVS3010/UVS3011 | RDE015V21 | 315 MHz |
| E-150 | 2011-2014 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| E-250 | 2010 | UVS3010/UVS3011 | RDE015V21 | 315 MHz |
| E-250 | 2010 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| E-250 | 2007-2009 | UVS3010/UVS3011 | RDE015V21 | 315 MHz |
| E-250 | 2011-2014 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| E-350 Super Duty | 2010 | UVS3010/UVS3011 | RDE015V21 | 315 MHz |
| E-350 Super Duty | 2010 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| E-350 Super Duty | 2007-2009 | | RDE015V21 | 315 MHz |
| E-350 Super Duty | 2011-2014 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| E-450 Super Duty | 2010 | UVS3010/UVS3011 | RDE015V21 | 315 MHz |
| E-450 Super Duty | 2010 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| E-450 Super Duty | 2007-2009 | UVS3010/UVS3011 | RDE015V21 | 315 MHz |
| E-450 Super Duty | 2011-2014 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| Edge | 2007-2010 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| Edge | 2011-2015 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| Escape | 2005-2008 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| Escape | 2009-2015 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| Expedition | 2005-2006 | UVS3010/UVS3011 | | 315 MHz |
| Expedition | 2007-2010 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |

| Make/Model | Year | IntelliSens Universal | OE Replacement | Frequency |
|---------------------|-----------|-----------------------|-------------------------|-----------|
| Expedition | 2011-2015 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| Explorer | 2016 | UVS3010/UVS3011 | | 315 MHz |
| Explorer | 2006-2010 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| Explorer | 2011-2015 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| Explorer Sport Trac | 2007-2010 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| F-150 | 2006-2008 | UVS3010/UVS3011 | RDE015V21 | 315 MHz |
| F-150 | 2006-2008 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| F-150 | 2009-2015 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| F-250 Super Duty | 2008-2010 | UVS3010/UVS3011 | RDE015V21 | 315 MHz |
| F-250 Super Duty | 2010-2016 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| F-350 Super Duty | 2008-2010 | UVS3010/UVS3011 | RDE015V21 | 315 MHz |
| F-350 Super Duty | 2010-2016 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| F-450 Super Duty | 2008-2010 | UVS3010/UVS3011 | RDE015V21 | 315 MHz |
| F-450 Super Duty | 2010-2016 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| Fiesta | 2011-2015 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| Five Hundred | 2006-2007 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| Flex | 2009-2010 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| Flex | 2011-2015 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| Focus | 2007-2009 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| Focus | 2010-2015 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| Freestar | 2004-2005 | UVS3010/UVS3011 | | 315 MHz |
| Freestar | 2006-2007 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| Fusion | 2007-2009 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| Fusion | 2010-2016 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| Mustang | 2006-2009 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| Mustang | 2010-2012 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| Mustang | 2013-2014 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| Mustang | 2013-2014 | UVS3010/UVS3011 | | 315 MHz |
| Mustang | 2015 | UVS3010/UVS3011 | | 315 MHz |
| Ranger | 2007-2011 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| Taurus | 2008-2010 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| Taurus | 2010-2015 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| Taurus | 2010-2015 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| Taurus X | 2008 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| Transit Connect | 2010-2015 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| Transit Connect | 2010-2015 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| Transit-150 | 2015 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| Transit-150 | 2015 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |

Application Listings

| Make/Model | Year | IntelliSens Universal | OE Replacement | Frequency |
|---------------------|-----------|-----------------------|-------------------------|-----------|
| Transit-250 | 2015 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| Transit-250 | 2015 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| Transit-350 | 2015 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| Transit-350 | 2015 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| Freightliner | | | | |
| Sprinter 2500 | 2014 | UVS4010/UVS4011 | | 433 MHz |
| Sprinter 2500 | 2007-2013 | UVS3010/UVS3011 | | 315 MHz |
| Sprinter 3500 | 2014 | UVS4010/UVS4011 | | 433 MHz |
| Sprinter 3500 | 2007-2013 | UVS3010/UVS3011 | | 315 MHz |
| GMC | | | | |
| Acadia | 2015 | UVS3010/UVS3011 | | 315 MHz |
| Acadia | 2007-2014 | UVS3010/UVS3011 | | 315 MHz |
| Canyon | 2015 | UVS3010/UVS3011 | | 315 MHz |
| Canyon | 2007-2012 | UVS3010/UVS3011 | | 315 MHz |
| Envoy | 2005-2009 | UVS3010/UVS3011 | | 315 MHz |
| Savana 1500 | 2008-2014 | UVS3010/UVS3011 | | 315 MHz |
| Savana 2500 | 2008-2015 | UVS3010/UVS3011 | | 315 MHz |
| Savana 3500 | 2008-2015 | UVS3010/UVS3011 | | 315 MHz |
| Sierra 1500 | 2004 | UVS3010/UVS3011 | | 315 MHz |
| Sierra 1500 | 2005-2015 | UVS3010/UVS3011 | | 315 MHz |
| Sierra 2500 HD | 2004 | UVS3010/UVS3011 | | 315 MHz |
| Sierra 2500 HD | 2005-2015 | UVS3010/UVS3011 | | 315 MHz |
| Sierra 3500 HD | 2004 | UVS3010/UVS3011 | | 315 MHz |
| Sierra 3500 HD | 2005-2015 | UVS3010/UVS3011 | | 315 MHz |
| Terrain | 2010-2015 | UVS3010/UVS3011 | | 315 MHz |
| Yukon | 2004 | UVS3010/UVS3011 | | 315 MHz |
| Yukon | 2005-2015 | UVS3010/UVS3011 | | 315 MHz |
| Yukon XL | 2015 | UVS3010/UVS3011 | | 315 MHz |
| Yukon XL 1500 | 2004 | UVS3010/UVS3011 | | 315 MHz |
| Yukon XL 1500 | 2005-2012 | UVS3010/UVS3011 | | 315 MHz |
| Yukon XL 2500 | 2004 | UVS3010/UVS3011 | | 315 MHz |
| Yukon XL 2500 | 2005-2011 | UVS3010/UVS3011 | | 315 MHz |
| Honda | | | | |
| Accord | 2008-2012 | UVS3010/UVS3011 | | 315 MHz |
| Accord Cross-tour | 2010-2012 | UVS3010/UVS3011 | | 315 MHz |
| Civic | 2008-2013 | UVS3010/UVS3011 | | 315 MHz |
| Crosstour | 2013-2015 | UVS3010/UVS3011 | | 315 MHz |
| CR-V | 2007-2013 | UVS3010/UVS3011 | | 315 MHz |
| CR-Z | 2011-2015 | UVS3010/UVS3011 | | 315 MHz |
| Element | 2009-2011 | UVS3010/UVS3011 | | 315 MHz |
| Fit | 2008-2014 | UVS3010/UVS3011 | | 315 MHz |
| Insight | 2010-2014 | UVS3010/UVS3011 | | 315 MHz |
| Odyssey | 2011-2015 | UVS3010/UVS3011 | | 315 MHz |
| S2000 | 2008-2009 | UVS3010/UVS3011 | | 315 MHz |
| Hummer | | | | |
| H2 | 2008-2010 | UVS3010/UVS3011 | | 315 MHz |
| H3 | 2006-2010 | UVS3010/UVS3011 | | 315 MHz |
| H3T | 2009-2010 | UVS3010/UVS3011 | | 315 MHz |
| Hyundai | | | | |
| Accent | 2015 | UVS4010/UVS4011 | | 433 MHz |
| Accent | 2006-2014 | UVS3010/UVS3011 | | 315 MHz |
| Azera | 2013 | UVS3010/UVS3011 | | 315 MHz |
| Azera | 2006-2012 | UVS3010/UVS3011 | RDE019V21 | 315 MHz |
| Elantra | 2010 | UVS3010/UVS3011 | RDE019V21 | 315 MHz |
| Elantra | 2009-2012 | UVS3010/UVS3011 | | 315 MHz |

| Make/Model | Year | IntelliSens Universal | OE Replacement | Frequency |
|-----------------|-----------|-----------------------|----------------|-----------|
| Elantra | 2011-2016 | UVS3010/UVS3011 | | 315 MHz |
| Elantra GT | 2013-2015 | UVS3010/UVS3011 | | 315 MHz |
| Entourage | 2007-2010 | UVS3010/UVS3011 | RDE020V21 | 315 MHz |
| Genesis Coupe | 2010-2015 | UVS3010/UVS3011 | | 315 MHz |
| Santa Fe | 2007-2008 | UVS3010/UVS3011 | RDE020V21 | 315 MHz |
| Santa Fe | 2009-2010 | UVS3010/UVS3011 | RDE019V21 | 315 MHz |
| Santa Fe | 2010-2012 | UVS3010/UVS3011 | | 315 MHz |
| Santa Fe | 2013-2016 | UVS3010/UVS3011 | | 315 MHz |
| Sonata | 2015 | UVS3010/UVS3011 | | 315 MHz |
| Sonata | 2007-2010 | UVS3010/UVS3011 | | 315 MHz |
| Sonata | 2011-2014 | UVS3010/UVS3011 | | 315 MHz |
| Tiburon | 2007-2008 | UVS3010/UVS3011 | | 315 MHz |
| Tucson | 2006-2013 | UVS3010/UVS3011 | | 315 MHz |
| Veloster | 2012-2015 | UVS3010/UVS3011 | | 315 MHz |
| Veracruz | 2007-2008 | UVS3010/UVS3011 | RDE020V21 | 315 MHz |
| Veracruz | 2008-2012 | UVS3010/UVS3011 | RDE019V21 | 315 MHz |
| Infiniti | | | | |
| EX35 | 2008-2012 | UVS3010/UVS3011 | | 315 MHz |
| EX37 | 2013 | UVS3010/UVS3011 | | 315 MHz |
| FX35 | 2003-2012 | UVS3010/UVS3011 | | 315 MHz |
| FX37 | 2013 | UVS3010/UVS3011 | | 315 MHz |
| FX45 | 2003-2008 | UVS3010/UVS3011 | | 315 MHz |
| FX50 | 2009-2013 | UVS3010/UVS3011 | | 315 MHz |
| G25 | 2011-2012 | UVS3010/UVS3011 | | 315 MHz |
| G35 | 2003-2008 | UVS3010/UVS3011 | | 315 MHz |
| G37 | 2008-2013 | UVS3010/UVS3011 | | 315 MHz |
| JX35 | 2013 | UVS4010/UVS4011 | | 433 MHz |
| M35 | 2006-2010 | UVS3010/UVS3011 | | 315 MHz |
| M35h | 2012-2013 | UVS3010/UVS3011 | | 315 MHz |
| M37 | 2011-2013 | UVS3010/UVS3011 | | 315 MHz |
| M45 | 2003-2011 | UVS3010/UVS3011 | | 315 MHz |
| M56 | 2011-2013 | UVS3010/UVS3011 | | 315 MHz |
| Q40 | 2015 | UVS3010/UVS3011 | | 315 MHz |
| Q45 | 2003-2006 | UVS3010/UVS3011 | | 315 MHz |
| Q50 | 2014-2015 | UVS3010/UVS3011 | | 315 MHz |
| Q60 | 2014-2015 | UVS3010/UVS3011 | | 315 MHz |
| Q70 | 2014-2015 | UVS3010/UVS3011 | | 315 MHz |
| QX4 | 2003 | UVS3010/UVS3011 | | 315 MHz |
| QX50 | 2014-2015 | UVS3010/UVS3011 | | 315 MHz |
| QX56 | 2004-2013 | UVS3010/UVS3011 | | 315 MHz |
| QX60 | 2014 | UVS4010/UVS4011 | | 433 MHz |
| QX70 | 2014-2016 | UVS3010/UVS3011 | | 315 MHz |
| QX80 | 2014-2015 | UVS3010/UVS3011 | | 315 MHz |
| Isuzu | | | | |
| Ascender | 2006-2008 | UVS3010/UVS3011 | | 315 MHz |
| i-290 | 2007-2009 | UVS3010/UVS3011 | | 315 MHz |
| i-370 | 2007-2009 | UVS3010/UVS3011 | | 315 MHz |
| Rodeo | 2004 | UVS4010/UVS4011 | | 433 MHz |
| Jaguar | | | | |
| F-Type | 2014-2016 | UVS3010/UVS3011 | | 315 MHz |
| S-Type | 2005-2008 | UVS3010/UVS3011 | | 315 MHz |
| Super V8 | 2005-2009 | UVS3010/UVS3011 | | 315 MHz |
| Vanden Plas | 2004-2009 | UVS3010/UVS3011 | | 315 MHz |
| XF | 2009-2015 | UVS3010/UVS3011 | | 315 MHz |
| XFR | 2010-2012 | UVS3010/UVS3011 | | 315 MHz |
| XJ | 2011 | UVS3010/UVS3011 | | 315 MHz |
| XJ | 2012-2015 | UVS3010/UVS3011 | | 315 MHz |
| XJ8 | 2004-2009 | UVS3010/UVS3011 | | 315 MHz |
| XJR | 2004-2009 | UVS3010/UVS3011 | | 315 MHz |

Application Listings

| Make/Model | Year | IntelliSens Universal | OE Replacement | Frequency |
|--------------------|-----------|-----------------------|----------------|-----------|
| XK | 2007-2012 | UVS3010/UVS3011 | | 315 MHz |
| XK | 2013-2015 | UVS3010/UVS3011 | | 315 MHz |
| XK8 | 2005-2006 | UVS3010/UVS3011 | | 315 MHz |
| XKR | 2013 | UVS3010/UVS3011 | | 315 MHz |
| XKR | 2005-2012 | UVS3010/UVS3011 | | 315 MHz |
| X-Type | 2008 | UVS3010/UVS3011 | | 315 MHz |
| Jeep | | | | |
| Cherokee | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| Commander | 2006-2007 | UVS3010/UVS3011 | | 315 MHz |
| Commander | 2008-2010 | UVS4010/UVS4011 | | 433 MHz |
| Compass | 2007-2013 | UVS3010/UVS3011 | | 315 MHz |
| Compass | 2014-2015 | UVS3010/UVS3011 | | 315 MHz |
| Grand Cherokee | 2002-2004 | UVS4010/UVS4011 | | 433 MHz |
| Grand Cherokee | 2005-2007 | UVS3010/UVS3011 | | 315 MHz |
| Grand Cherokee | 2008-2015 | UVS4010/UVS4011 | | 433 MHz |
| Liberty | 2004 | UVS4010/UVS4011 | | 433 MHz |
| Liberty | 2009 | UVS4010/UVS4011 | | 433 MHz |
| Liberty | 2005-2012 | UVS3010/UVS3011 | | 315 MHz |
| Patriot | 2007-2013 | UVS3010/UVS3011 | | 315 MHz |
| Patriot | 2014-2015 | UVS3010/UVS3011 | | 315 MHz |
| Wrangler | 2007-2008 | UVS3010/UVS3011 | | 315 MHz |
| Wrangler | 2009-2010 | UVS4010/UVS4011 | | 433 MHz |
| Wrangler | 2009-2012 | UVS3010/UVS3011 | | 315 MHz |
| Wrangler | 2013-2015 | UVS4010/UVS4011 | | 433 MHz |
| Kia | | | | |
| Amanti | 2007-2009 | UVS3010/UVS3011 | | 315 MHz |
| Borrego | 2009-2011 | UVS3010/UVS3011 | | 315 MHz |
| Cadenza | 2014 | UVS4010/UVS4011 | | 433 MHz |
| Cadenza | 2014-2015 | UVS3010/UVS3011 | | 315 MHz |
| Forte | 2010-2013 | UVS3010/UVS3011 | | 315 MHz |
| Magentis | 2008-2010 | UVS3010/UVS3011 | RDE019V21 | 315 MHz |
| Optima | 2006-2010 | UVS3010/UVS3011 | RDE019V21 | 315 MHz |
| Optima | 2011-2013 | UVS3010/UVS3011 | | 315 MHz |
| Optima | 2014-2015 | UVS3010/UVS3011 | | 315 MHz |
| Rio | 2007-2015 | UVS3010/UVS3011 | | 315 MHz |
| Rio5 | 2007-2015 | UVS3010/UVS3011 | | 315 MHz |
| Rondo | 2006-2010 | UVS3010/UVS3011 | RDE019V21 | 315 MHz |
| Sedona | 2006-2008 | UVS3010/UVS3011 | RDE020V21 | 315 MHz |
| Sedona | 2009-2015 | UVS3010/UVS3011 | RDE019V21 | 315 MHz |
| Sorento | 2014 | UVS4010/UVS4011 | | 433 MHz |
| Sorento | 2015 | UVS3010/UVS3011 | | 315 MHz |
| Sorento | 2016 | UVS4010/UVS4011 | | 433 MHz |
| Sorento | 2005-2009 | UVS3010/UVS3011 | | 315 MHz |
| Sorento | 2011-2014 | UVS3010/UVS3011 | | 315 MHz |
| Soul | 2010-2013 | UVS3010/UVS3011 | | 315 MHz |
| Soul | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| Spectra | 2006-2009 | UVS3010/UVS3011 | | 315 MHz |
| Spectra5 | 2007-2009 | UVS3010/UVS3011 | | 315 MHz |
| Sportage | 2005-2013 | UVS3010/UVS3011 | | 315 MHz |
| Lamborghini | | | | |
| Aventador | 2011-2015 | UVS2000 | RDE011V21 | 433 MHz |
| Gallardo | 2007-2014 | UVS2000 | RDE011V21 | 433 MHz |
| Huracan | 2015 | UVS2000 | RDE011V21 | 433 MHz |
| Murcielago | 2007-2011 | UVS2000 | RDE011V21 | 433 MHz |
| Land Rover | | | | |
| LR2 | 2008-2015 | UVS3010/UVS3011 | | 315 MHz |
| LR3 | 2005 | | RDE003V21 | 433 MHz |
| LR3 | 2006-2009 | UVS3010/UVS3011 | | 315 MHz |
| LR4 | 2010-2013 | UVS3010/UVS3011 | | 315 MHz |

| Make/Model | Year | IntelliSens Universal | OE Replacement | Frequency |
|--------------------|-----------|-----------------------|-------------------------|-----------|
| Range Rover | 2002-2005 | | RDE003V21 | 433 MHz |
| Range Rover | 2006-2011 | UVS3010/UVS3011 | | 315 MHz |
| Range Rover | 2012-2014 | UVS3010/UVS3011 | | 315 MHz |
| Range Rover Evoque | 2012-2015 | UVS3010/UVS3011 | | 315 MHz |
| Range Rover Sport | 2006-2011 | UVS3010/UVS3011 | | 315 MHz |
| Range Rover Sport | 2012-2014 | UVS3010/UVS3011 | | 315 MHz |
| Lexus | | | | |
| CT200h | 2011-2015 | UVS3010/UVS3011 | | 315 MHz |
| ES300h | 2013-2015 | UVS3010/UVS3011 | | 315 MHz |
| ES350 | 2007-2015 | UVS3010/UVS3011 | | 315 MHz |
| GS300 | 2005-2006 | UVS3010/UVS3011 | | 315 MHz |
| GS350 | 2007-2015 | UVS3010/UVS3011 | | 315 MHz |
| GS430 | 2005-2007 | UVS3010/UVS3011 | | 315 MHz |
| GS450h | 2007-2015 | UVS3010/UVS3011 | | 315 MHz |
| GS460 | 2008-2012 | UVS3010/UVS3011 | | 315 MHz |
| GX460 | 2010-2015 | UVS3010/UVS3011 | | 315 MHz |
| GX470 | 2004-2009 | UVS3010/UVS3011 | | 315 MHz |
| HS250h | 2010-2012 | UVS3010/UVS3011 | | 315 MHz |
| IS F | 2008-2015 | UVS3010/UVS3011 | | 315 MHz |
| IS250 | 2006-2015 | UVS3010/UVS3011 | | 315 MHz |
| IS350 | 2006-2015 | UVS3010/UVS3011 | | 315 MHz |
| LFA | 2012-2015 | UVS3010/UVS3011 | | 315 MHz |
| LS460 | 2007-2015 | UVS3010/UVS3011 | | 315 MHz |
| LS600h | 2008-2014 | UVS3010/UVS3011 | | 315 MHz |
| LX470 | 2005-2007 | UVS3010/UVS3011 | | 315 MHz |
| LX570 | 2008-2015 | UVS3010/UVS3011 | | 315 MHz |
| NX200t | 2015 | UVS3010/UVS3011 | | 315 MHz |
| NX300h | 2015 | UVS3010/UVS3011 | | 315 MHz |
| RC F | 2015 | UVS3010/UVS3011 | | 315 MHz |
| RC350 | 2015 | UVS3010/UVS3011 | | 315 MHz |
| RX330 | 2006 | UVS3010/UVS3011 | | 315 MHz |
| RX350 | 2007-2015 | UVS3010/UVS3011 | | 315 MHz |
| RX400h | 2006-2009 | UVS3010/UVS3011 | | 315 MHz |
| RX450h | 2010-2015 | UVS3010/UVS3011 | | 315 MHz |
| SC430 | 2006-2010 | UVS3010/UVS3011 | | 315 MHz |
| Lincoln | | | | |
| Mark LT | 2007-2008 | UVS3010/UVS3011 | RDE015V21 | 315 MHz |
| Mark LT | 2007-2008 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| MKC | 2015 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| MKS | 2009-2010 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| MKS | 2011-2015 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| MKT | 2010 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| MKT | 2011-2015 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| MKX | 2007-2010 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| MKX | 2011-2015 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| MKZ | 2007-2009 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| MKZ | 2010-2016 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| Navigator | 2005-2006 | UVS3010/UVS3011 | | 315 MHz |
| Navigator | 2007-2010 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| Navigator | 2011-2015 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| Town Car | 2006-2011 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |

Application Listings

| Make/Model | Year | IntelliSens Universal | OE Replacement | Frequency |
|----------------------|-----------|-----------------------|-------------------------|-----------|
| Zephyr | 2006 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| Lotus | | | | |
| Elise | 2008-2011 | UVS4010/UVS4011 | | 433 MHz |
| Evora | 2010-2014 | UVS4010/UVS4011 | | 433 MHz |
| Exige | 2008-2010 | UVS4010/UVS4011 | | 433 MHz |
| Maserati | | | | |
| Coupe | 2004-2009 | | RDE001V21 | 433 MHz |
| Coupe | 2009-2011 | UVS2000 | RDE011V21 | 433 MHz |
| GranCabrio | 2010-2013 | UVS2000 | RDE011V21 | 433 MHz |
| GranSport | 2005 | UVS2000 | RDE011V21 | 433 MHz |
| GranTurismo | 2008-2013 | UVS2000 | RDE011V21 | 433 MHz |
| Quattroporte | 2004-2009 | | RDE001V21 | 433 MHz |
| Quattroporte | 2010-2013 | UVS2000 | RDE011V21 | 433 MHz |
| Spyder | 2002-2005 | UVS2000 | RDE011V21 | 433 MHz |
| Maybach | | | | |
| 57 | 2003-2011 | | RDE001V21 | 433 MHz |
| 57 | 2003-2011 | | RDE004V21 | 315 MHz |
| 62 | 2003-2011 | | RDE001V21 | 433 MHz |
| 62 | 2003-2011 | | RDE004V21 | 315 MHz |
| Mazda | | | | |
| 2 | 2011-2012 | UVS3010/UVS3011 | | 315 MHz |
| 2 | 2012-2014 | UVS3010/UVS3011 | | 315 MHz |
| 3 | 2004-2012 | UVS3010/UVS3011 | | 315 MHz |
| 3 | 2012-2013 | UVS3010/UVS3011 | | 315 MHz |
| 5 | 2006-2015 | UVS3010/UVS3011 | | 315 MHz |
| 6 | 2005-2013 | UVS3010/UVS3011 | | 315 MHz |
| 6 | 2005-2013 | UVS3010/UVS3011 | | 315 MHz |
| B2300 | 2007-2009 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| B3000 | 2007-2008 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| B4000 | 2007-2009 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| CX-7 | 2007-2012 | UVS3010/UVS3011 | | 315 MHz |
| CX-9 | 2007-2015 | UVS3010/UVS3011 | | 315 MHz |
| MX-5 Miata | 2006-2008 | UVS3010/UVS3011 | | 315 MHz |
| MX-5 Miata | 2009-2014 | UVS3010/UVS3011 | | 315 MHz |
| MX-5 Miata | 2015 | UVS3010/UVS3011 | | 315 MHz |
| RX-8 | 2004-2011 | UVS3010/UVS3011 | | 315 MHz |
| Tribute | 2006 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| Tribute | 2011 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| Tribute | 2011 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| Tribute | 2008-2010 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| Mercedes-Benz | | | | |
| B Electric Drive | 2014 | UVS4010/UVS4011 | | 433 MHz |
| C250 | 2012-2014 | UVS4010/UVS4011 | | 433 MHz |
| C250 | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| C300 | 2008-2014 | UVS4010/UVS4011 | | 433 MHz |
| C300 | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| C350 | 2007-2014 | UVS4010/UVS4011 | | 433 MHz |
| C350 | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| C400 | 2015 | UVS4010/UVS4011 | | 433 MHz |
| C63 AMG | 2008-2014 | UVS4010/UVS4011 | | 433 MHz |
| C63 AMG | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| CL500 | 2000-2006 | | RDE004V21 | 315 MHz |
| CL55 AMG | 2001-2006 | | RDE004V21 | 315 MHz |
| CL550 | 2014 | UVS4010/UVS4011 | | 433 MHz |
| CL550 | 2007-2009 | UVS3010/UVS3011 | RDE004V21 | 315 MHz |
| CL550 | 2010-2014 | UVS4010/UVS4011 | | 433 MHz |
| CL600 | 2014 | UVS4010/UVS4011 | | 433 MHz |

| Make/Model | Year | IntelliSens Universal | OE Replacement | Frequency |
|------------|-----------|-----------------------|----------------|-----------|
| CL600 | 2001-2009 | UVS3010/UVS3011 | RDE004V21 | 315 MHz |
| CL600 | 2010-2014 | UVS4010/UVS4011 | | 433 MHz |
| CL63 AMG | 2014 | UVS4010/UVS4011 | | 433 MHz |
| CL63 AMG | 2008-2009 | UVS3010/UVS3011 | RDE004V21 | 315 MHz |
| CL63 AMG | 2010-2014 | UVS4010/UVS4011 | | 433 MHz |
| CL65 AMG | 2014 | UVS4010/UVS4011 | | 433 MHz |
| CL65 AMG | 2005-2009 | UVS3010/UVS3011 | RDE004V21 | 315 MHz |
| CL65 AMG | 2010-2014 | UVS4010/UVS4011 | | 433 MHz |
| CLA250 | 2014 | UVS4010/UVS4011 | | 433 MHz |
| CLA250 | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| CLA45 AMG | 2014 | UVS4010/UVS4011 | | 433 MHz |
| CLA45 AMG | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| CLK350 | 2006-2007 | | RDE004V21 | 315 MHz |
| CLK350 | 2006-2009 | UVS4010/UVS4011 | | 433 MHz |
| CLK500 | 2006 | UVS4010/UVS4011 | | 433 MHz |
| CLK55 AMG | 2006 | UVS4010/UVS4011 | | 433 MHz |
| CLK550 | 2007-2009 | UVS4010/UVS4011 | | 433 MHz |
| CLK63 AMG | 2007-2009 | UVS4010/UVS4011 | | 433 MHz |
| CLS400 | 2015 | UVS4010/UVS4011 | | 433 MHz |
| CLS500 | 2006 | UVS3010/UVS3011 | RDE004V21 | 315 MHz |
| CLS55 AMG | 2006 | UVS3010/UVS3011 | RDE004V21 | 315 MHz |
| CLS550 | 2007-2011 | UVS3010/UVS3011 | RDE004V21 | 315 MHz |
| CLS550 | 2012-2014 | UVS4010/UVS4011 | | 433 MHz |
| CLS550 | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| CLS63 AMG | 2007-2011 | UVS3010/UVS3011 | RDE004V21 | 315 MHz |
| CLS63 AMG | 2012-2014 | UVS4010/UVS4011 | | 433 MHz |
| CLS63 AMG | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| E250 | 2014 | UVS4010/UVS4011 | | 433 MHz |
| E250 | 2014-2016 | UVS4010/UVS4011 | | 433 MHz |
| E320 | 2000-2006 | | RDE004V21 | 315 MHz |
| E320 | 2006-2009 | UVS3010/UVS3011 | RDE004V21 | 315 MHz |
| E350 | 2006-2009 | UVS3010/UVS3011 | RDE004V21 | 315 MHz |
| E350 | 2010-2014 | UVS4010/UVS4011 | | 433 MHz |
| E350 | 2014-2016 | UVS4010/UVS4011 | | 433 MHz |
| E400 | 2014 | UVS4010/UVS4011 | | 433 MHz |
| E400 | 2014-2016 | UVS4010/UVS4011 | | 433 MHz |
| E430 | 2000 | | RDE001V21 | 433 MHz |
| E430 | 2000-2002 | | RDE004V21 | 315 MHz |
| E500 | 2006 | UVS3010/UVS3011 | | 315 MHz |
| E500 | 2003-2006 | | RDE004V21 | 315 MHz |
| E55 AMG | 2006 | UVS3010/UVS3011 | | 315 MHz |
| E55 AMG | 1999-2006 | | RDE004V21 | 315 MHz |
| E550 | 2007-2009 | UVS3010/UVS3011 | RDE004V21 | 315 MHz |
| E550 | 2010-2014 | UVS4010/UVS4011 | | 433 MHz |
| E550 | 2014-2016 | UVS4010/UVS4011 | | 433 MHz |
| E63 AMG | 2007-2009 | UVS3010/UVS3011 | RDE004V21 | 315 MHz |
| E63 AMG | 2010-2014 | UVS4010/UVS4011 | | 433 MHz |
| E63 AMG | 2014-2016 | UVS4010/UVS4011 | | 433 MHz |
| G500 | 2007-2008 | UVS4010/UVS4011 | | 433 MHz |
| G55 AMG | 2007-2011 | UVS4010/UVS4011 | | 433 MHz |
| G550 | 2015 | UVS4010/UVS4011 | | 433 MHz |
| G550 | 2009-2014 | UVS4010/UVS4011 | | 433 MHz |
| G63 AMG | 2015 | UVS4010/UVS4011 | | 433 MHz |
| G63 AMG | 2013-2014 | UVS4010/UVS4011 | | 433 MHz |
| GL350 | 2010-2014 | UVS4010/UVS4011 | | 433 MHz |
| GL350 | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| GL450 | 2010-2014 | UVS4010/UVS4011 | | 433 MHz |
| GL450 | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| GL550 | 2010-2014 | UVS4010/UVS4011 | | 433 MHz |

Application Listings

| Make/Model | Year | IntelliSens Universal | OE Replacement | Frequency |
|------------|-----------|-----------------------|----------------|-----------|
| GL63 AMG | 2013-2014 | UVS4010/UVS4011 | | 433 MHz |
| GL63 AMG | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| GLA250 | 2015 | UVS4010/UVS4011 | | 433 MHz |
| GLA45 AMG | 2015 | UVS4010/UVS4011 | | 433 MHz |
| GLK250 | 2014 | UVS4010/UVS4011 | | 433 MHz |
| GLK250 | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| GLK350 | 2010-2014 | UVS4010/UVS4011 | | 433 MHz |
| GLK350 | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| ML250 | 2015 | UVS4010/UVS4011 | | 433 MHz |
| ML350 | 2010-2014 | UVS4010/UVS4011 | | 433 MHz |
| ML350 | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| ML400 | 2015 | UVS4010/UVS4011 | | 433 MHz |
| ML450 | 2010-2011 | UVS4010/UVS4011 | | 433 MHz |
| ML550 | 2010-2014 | UVS4010/UVS4011 | | 433 MHz |
| ML550 | 2014 | UVS4010/UVS4011 | | 433 MHz |
| ML63 AMG | 2010-2014 | UVS4010/UVS4011 | | 433 MHz |
| ML63 AMG | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| R350 | 2012 | UVS4010/UVS4011 | | 433 MHz |
| S350 | 2006 | | RDE004V21 | 315 MHz |
| S400 | 2010 | UVS3010/UVS3011 | RDE004V21 | 315 MHz |
| S400 | 2010-2013 | UVS4010/UVS4011 | | 433 MHz |
| S430 | 2000-2006 | | RDE004V21 | 315 MHz |
| S450 | 2009 | UVS3010/UVS3011 | RDE004V21 | 315 MHz |
| S500 | 2000 | | RDE001V21 | 433 MHz |
| S500 | 2000-2006 | | RDE004V21 | 315 MHz |
| S55 AMG | 2001-2006 | | RDE004V21 | 315 MHz |
| S550 | 2007-2009 | UVS3010/UVS3011 | RDE004V21 | 315 MHz |
| S550 | 2010-2014 | UVS4010/UVS4011 | | 433 MHz |
| S550 | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| S600 | 2001-2007 | | RDE004V21 | 315 MHz |
| S600 | 2007-2009 | UVS3010/UVS3011 | RDE004V21 | 315 MHz |
| S600 | 2010-2013 | UVS4010/UVS4011 | | 433 MHz |
| S600 | 2015-2016 | UVS4010/UVS4011 | | 433 MHz |
| S63 AMG | 2008-2009 | UVS3010/UVS3011 | RDE004V21 | 315 MHz |
| S63 AMG | 2011-2014 | UVS4010/UVS4011 | | 433 MHz |
| S63 AMG | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| S65 AMG | 2006 | | RDE004V21 | 315 MHz |
| S65 AMG | 2007-2009 | UVS3010/UVS3011 | RDE004V21 | 315 MHz |
| S65 AMG | 2010-2013 | UVS4010/UVS4011 | | 433 MHz |
| S65 AMG | 2015 | UVS4010/UVS4011 | | 433 MHz |
| SL400 | 2015 | UVS4010/UVS4011 | | 433 MHz |
| SL500 | 2006 | UVS3010/UVS3011 | | 315 MHz |
| SL500 | 2000-2006 | | RDE004V21 | 315 MHz |
| SL55 AMG | 2003-2008 | | RDE004V21 | 315 MHz |
| SL55 AMG | 2006-2008 | UVS3010/UVS3011 | | 315 MHz |
| SL550 | 2007-2009 | UVS3010/UVS3011 | RDE004V21 | 315 MHz |
| SL550 | 2011-2012 | UVS3010/UVS3011 | RDE004V21 | 315 MHz |
| SL550 | 2013-2014 | UVS4010/UVS4011 | | 433 MHz |
| SL550 | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| SL600 | 2000-2009 | | RDE004V21 | 315 MHz |
| SL600 | 2006-2009 | UVS3010/UVS3011 | | 315 MHz |
| SL63 AMG | 2009 | UVS3010/UVS3011 | RDE004V21 | 315 MHz |
| SL63 AMG | 2013 | UVS4010/UVS4011 | | 433 MHz |
| SL63 AMG | 2011-2012 | UVS3010/UVS3011 | RDE004V21 | 315 MHz |
| SL63 AMG | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| SL65 AMG | 2011 | UVS3010/UVS3011 | RDE004V21 | 315 MHz |
| SL65 AMG | 2005-2009 | | RDE004V21 | 315 MHz |
| SL65 AMG | 2006-2009 | UVS3010/UVS3011 | | 315 MHz |
| SL65 AMG | 2013-2014 | UVS4010/UVS4011 | | 433 MHz |

| Make/Model | Year | IntelliSens Universal | OE Replacement | Frequency |
|-------------------|-----------|-----------------------|-------------------------|-----------|
| SL65 AMG | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| SLK250 | 2012-2014 | UVS4010/UVS4011 | | 433 MHz |
| SLK250 | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| SLK280 | 2007-2008 | UVS4010/UVS4011 | | 433 MHz |
| SLK300 | 2009-2011 | UVS4010/UVS4011 | | 433 MHz |
| SLK350 | 2007-2014 | UVS4010/UVS4011 | | 433 MHz |
| SLK350 | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| SLK55 AMG | 2007-2010 | UVS4010/UVS4011 | | 433 MHz |
| SLK55 AMG | 2012-2014 | UVS4010/UVS4011 | | 433 MHz |
| SLK55 AMG | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| SLR McLaren | 2004-2009 | | RDE001V21 | 433 MHz |
| SLR McLaren | 2008-2009 | UVS3010/UVS3011 | | 315 MHz |
| SLS AMG | 2011-2014 | UVS4010/UVS4011 | | 433 MHz |
| SLS AMG | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| Sprinter 2500 | 2010-2013 | UVS3010/UVS3011 | | 315 MHz |
| Sprinter 2500 | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| Sprinter 3500 | 2010-2013 | UVS3010/UVS3011 | | 315 MHz |
| Sprinter 3500 | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| Mercury | | | | |
| Grand Marquis | 2006-2011 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| Mariner | 2005-2008 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| Mariner | 2009-2011 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| Milan | 2007 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| Milan | 2007-2009 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| Milan | 2010-2011 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |
| Montego | 2006-2007 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| Monterey | 2004-2005 | UVS3010/UVS3011 | | 315 MHz |
| Monterey | 2006-2007 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| Mountaineer | 2006-2010 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| Sable | 2008-2009 | UVS3010/UVS3011 | RDE014V21 | 315 MHz |
| Mini | | | | |
| Cooper | 2007-2009 | UVS2000 | RDE008V21 | 433 MHz |
| Cooper | 2010-2014 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| Cooper | 2014-2015 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| Cooper Countryman | 2011-2014 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| Cooper Countryman | 2014-2015 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| Cooper Pace-man | 2013-2014 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| Cooper Pace-man | 2014-2015 | UVS4010/UVS4011 | RDE017V21 | 433 MHz |
| Mitsubishi | | | | |
| Eclipse | 2006-2007 | UVS3010/UVS3011 | | 315 MHz |
| Eclipse | 2006-2007 | UVS3010/UVS3011 | | 315 MHz |
| Eclipse | 2008-2012 | UVS3010/UVS3011 | | 315 MHz |
| Endeavor | 2004-2006 | UVS4010/UVS4011 | | 433 MHz |
| Endeavor | 2006-2009 | UVS3010/UVS3011 | | 315 MHz |
| Endeavor | 2010-2011 | UVS3010/UVS3011 | | 315 MHz |
| Galant | 2004-2006 | UVS4010/UVS4011 | | 433 MHz |
| Galant | 2007-2012 | UVS3010/UVS3011 | | 315 MHz |
| i-MiEV | 2012-2014 | UVS3010/UVS3011 | | 315 MHz |
| Lancer | 2008-2015 | UVS3010/UVS3011 | | 315 MHz |
| Mirage | 2014-2015 | UVS3010/UVS3011 | | 315 MHz |
| Montero | 2003-2006 | UVS3010/UVS3011 | | 315 MHz |
| Montero Sport | 2003-2004 | UVS3010/UVS3011 | | 315 MHz |
| Outlander | 2006-2015 | UVS3010/UVS3011 | | 315 MHz |
| Outlander Sport | 2011-2015 | UVS3010/UVS3011 | | 315 MHz |

Application Listings

| Make/Model | Year | IntelliSens Universal | OE Replacement | Frequency |
|------------------|-----------|-----------------------|----------------|-----------|
| Raider | 2008-2009 | UVS3010/UVS3011 | | 315 MHz |
| Nissan | | | | |
| 350Z | 2003-2009 | UVS3010/UVS3011 | | 315 MHz |
| 370Z | 2009-2016 | UVS3010/UVS3011 | | 315 MHz |
| Altima | 2013 | UVS4010/UVS4011 | | 433 MHz |
| Altima | 2013 | UVS3010/UVS3011 | | 315 MHz |
| Altima | 2014 | UVS4010/UVS4011 | | 433 MHz |
| Altima | 2006-2012 | UVS3010/UVS3011 | | 315 MHz |
| Armada | 2005-2016 | UVS3010/UVS3011 | | 315 MHz |
| Cube | 2009-2014 | UVS3010/UVS3011 | | 315 MHz |
| Frontier | 2003-2016 | UVS3010/UVS3011 | | 315 MHz |
| GT-R | 2009-2016 | UVS3010/UVS3011 | | 315 MHz |
| Juke | 2011-2015 | UVS3010/UVS3011 | | 315 MHz |
| Leaf | 2011-2015 | UVS3010/UVS3011 | | 315 MHz |
| Maxima | 2006-2015 | UVS3010/UVS3011 | | 315 MHz |
| Murano | 2003-2015 | UVS3010/UVS3011 | | 315 MHz |
| NV1500 | 2012-2015 | UVS3010/UVS3011 | | 315 MHz |
| NV200 | 2013-2015 | UVS3010/UVS3011 | | 315 MHz |
| NV2500 | 2012-2015 | UVS3010/UVS3011 | | 315 MHz |
| NV3500 | 2012-2015 | UVS3010/UVS3011 | | 315 MHz |
| Pathfinder | 2003-2012 | UVS3010/UVS3011 | | 315 MHz |
| Pathfinder | 2013-2014 | UVS4010/UVS4011 | | 433 MHz |
| Quest | 2004-2015 | UVS3010/UVS3011 | | 315 MHz |
| Rogue | 2008-2013 | UVS3010/UVS3011 | | 315 MHz |
| Rogue | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| Rogue Select | 2014-2015 | UVS3010/UVS3011 | | 315 MHz |
| Sentra | 2007-2015 | UVS3010/UVS3011 | | 315 MHz |
| Titan | 2004-2015 | UVS3010/UVS3011 | | 315 MHz |
| Versa | 2007-2015 | UVS3010/UVS3011 | | 315 MHz |
| Versa Hatch-back | 2011 | UVS3010/UVS3011 | | 315 MHz |
| Versa Note | 2014-2015 | UVS3010/UVS3011 | | 315 MHz |
| Xterra | 2003-2015 | UVS3010/UVS3011 | | 315 MHz |
| Pontiac | | | | |
| G5 | 2008-2010 | UVS3010/UVS3011 | | 315 MHz |
| G6 | 2008-2010 | UVS3010/UVS3011 | | 315 MHz |
| G8 | 2008-2009 | UVS3010/UVS3011 | | 315 MHz |
| Grand Prix | 2007-2008 | UVS3010/UVS3011 | | 315 MHz |
| Montana | 2008-2009 | UVS3010/UVS3011 | | 315 MHz |
| Solstice | 2008-2009 | UVS3010/UVS3011 | | 315 MHz |
| Torrent | 2007-2009 | UVS3010/UVS3011 | | 315 MHz |
| Vibe | 2008-2010 | UVS3010/UVS3011 | | 315 MHz |
| Porsche | | | | |
| 911 | 2005-2008 | | RDE001V21 | 433 MHz |
| 911 | 2005-2008 | | RDE004V21 | 315 MHz |
| 911 | 2009-2015 | UVS2000 | RDE011V21 | 433 MHz |
| 911 | 2010-2014 | | RDE022V21 | 315 MHz |
| 918 Spyder | 2015 | UVS2000 | RDE011V21 | 433 MHz |
| Boxster | 2005-2008 | | RDE001V21 | 433 MHz |
| Boxster | 2005-2008 | | RDE004V21 | 315 MHz |
| Boxster | 2008-2015 | UVS2000 | RDE011V21 | 433 MHz |
| Boxster | 2009-2015 | | RDE022V21 | 315 MHz |
| Carrera GT | 2004-2006 | | RDE001V21 | 433 MHz |
| Carrera GT | 2004-2006 | | RDE004V21 | 315 MHz |
| Cayenne | 2003-2006 | | RDE005V21 | 433 MHz |
| Cayenne | 2007-2016 | UVS2000 | RDE011V21 | 433 MHz |
| Cayenne | 2008-2015 | | RDE022V21 | 315 MHz |
| Cayman | 2006-2008 | | RDE001V21 | 433 MHz |
| Cayman | 2006-2008 | | RDE004V21 | 315 MHz |

| Make/Model | Year | IntelliSens Universal | OE Replacement | Frequency |
|--------------------|-----------|-----------------------|----------------|-----------|
| Cayman | 2009-2012 | UVS1000 | RDE022V21 | 315 MHz |
| Cayman | 2009-2015 | UVS2000 | RDE011V21 | 433 MHz |
| Macan | 2015 | UVS4010/UVS4011 | RDE018V21 | 433 MHz |
| Panamera | 2010-2014 | UVS1000 | RDE022V21 | 315 MHz |
| Panamera | 2010-2012 | UVS2000 | RDE011V21 | 433 MHz |
| Panamera | 2013-2014 | UVS4010/UVS4011 | RDE018V21 | 433 MHz |
| Panamera | 2015 | UVS2000 | RDE011V21 | 433 MHz |
| Ram | | | | |
| 1500 | 2011-2015 | UVS4010/UVS4011 | | 433 MHz |
| 2500 | 2011-2015 | UVS4010/UVS4011 | | 433 MHz |
| 3500 | 2011-2013 | UVS4010/UVS4011 | | 433 MHz |
| 3500 | 2014-2015 | UVS4010/UVS4011 | | 433 MHz |
| C/V | 2012-2015 | UVS4010/UVS4011 | | 433 MHz |
| Rolls Royce | | | | |
| Ghost | 2010-2014 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| Phantom | 2007-2011 | UVS2000 | RDE008V21 | 433 MHz |
| Phantom | 2012-2014 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| Wraith | 2014 | UVS4010/UVS4011 | RDE012V21 | 433 MHz |
| Saab | | | | |
| 9-3 | 2003-2012 | UVS4010/UVS4011 | | 433 MHz |
| 9-4X | 2011 | UVS3010/UVS3011 | | 315 MHz |
| 9-5 | 2003-2009 | UVS4010/UVS4011 | | 433 MHz |
| 9-5 | 2010-2012 | UVS3010/UVS3011 | | 315 MHz |
| 9-7x | 2005-2009 | UVS3010/UVS3011 | | 315 MHz |
| Saturn | | | | |
| Astra | 2008-2009 | UVS4010/UVS4011 | | 433 MHz |
| Aura | 2007-2010 | UVS3010/UVS3011 | | 315 MHz |
| Outlook | 2007-2010 | UVS3010/UVS3011 | | 315 MHz |
| Sky | 2008-2009 | UVS3010/UVS3011 | | 315 MHz |
| Vue | 2007-2010 | UVS3010/UVS3011 | | 315 MHz |
| Scion | | | | |
| iQ | 2012-2015 | UVS3010/UVS3011 | | 315 MHz |
| tC | 2006-2015 | UVS3010/UVS3011 | | 315 MHz |
| xB | 2007-2015 | UVS3010/UVS3011 | | 315 MHz |
| xD | 2008-2014 | UVS3010/UVS3011 | | 315 MHz |
| Smart | | | | |
| Fortwo | 2008-2015 | UVS4010/UVS4011 | | 433 MHz |
| SRT | | | | |
| Viper | 2013-2015 | UVS4010/UVS4011 | | 433 MHz |
| Subaru | | | | |
| B9 Tribeca | 2006-2008 | UVS3010/UVS3011 | | 315 MHz |
| BRZ | 2013-2015 | UVS3010/UVS3011 | | 315 MHz |
| Forester | 2008-2015 | UVS3010/UVS3011 | | 315 MHz |
| Impreza | 2015 | UVS3010/UVS3011 | | 315 MHz |
| Legacy | 2004-2015 | UVS3010/UVS3011 | | 315 MHz |
| Outback | 2004-2015 | UVS3010/UVS3011 | | 315 MHz |
| Tribeca | 2008-2014 | UVS3010/UVS3011 | | 315 MHz |
| WRX | 2015-2016 | UVS3010/UVS3011 | | 315 MHz |
| XV Crosstrek | 2013-2015 | UVS3010/UVS3011 | | 315 MHz |
| Suzuki | | | | |
| Equator | 2009-2010 | UVS3010/UVS3011 | | 315 MHz |
| Equator | 2011-2013 | UVS3010/UVS3011 | | 315 MHz |
| Forenza | 2007-2008 | UVS3010/UVS3011 | | 315 MHz |
| Grand Vitara | 2005-2013 | UVS3010/UVS3011 | | 315 MHz |
| Kizashi | 2010-2013 | UVS3010/UVS3011 | | 315 MHz |
| Reno | 2007-2008 | UVS3010/UVS3011 | | 315 MHz |
| SX4 | 2007-2013 | UVS3010/UVS3011 | | 315 MHz |
| XL-7 | 2005-2006 | UVS3010/UVS3011 | | 315 MHz |
| XL-7 | 2007-2009 | UVS3010/UVS3011 | | 315 MHz |

Application Listings

| Make/Model | Year | IntelliSens Universal | OE Replacement | Frequency |
|-------------------|-----------|-----------------------|----------------|-----------|
| Tesla | | | | |
| Roadster | 2008-2010 | UVS2000 | RDE011V21 | 433 MHz |
| Toyota | | | | |
| 4Runner | 2003-2015 | UVS3010/UVS3011 | | 315 MHz |
| Avalon | 2006-2015 | UVS3010/UVS3011 | | 315 MHz |
| Camry | 2015 | UVS3010/UVS3011 | | 315 MHz |
| Camry | 2007-2014 | UVS3010/UVS3011 | | 315 MHz |
| Corolla | 2007-2015 | UVS3010/UVS3011 | | 315 MHz |
| FJ Cruiser | 2007-2014 | UVS3010/UVS3011 | | 315 MHz |
| Highlander | 2007-2015 | UVS3010/UVS3011 | | 315 MHz |
| Land Cruiser | 2005-2015 | UVS3010/UVS3011 | | 315 MHz |
| Matrix | 2007-2014 | UVS3010/UVS3011 | | 315 MHz |
| Prius | 2006-2015 | UVS3010/UVS3011 | | 315 MHz |
| Prius C | 2012-2015 | UVS3010/UVS3011 | | 315 MHz |
| Prius V | 2012-2015 | UVS3010/UVS3011 | | 315 MHz |
| RAV4 | 2006-2015 | UVS3010/UVS3011 | | 315 MHz |
| Sequoia | 2004-2015 | UVS3010/UVS3011 | | 315 MHz |
| Sienna | 2007-2015 | UVS3010/UVS3011 | | 315 MHz |
| Solara | 2006-2008 | UVS3010/UVS3011 | | 315 MHz |
| Tacoma | 2005-2015 | UVS3010/UVS3011 | | 315 MHz |
| Tundra | 2005-2015 | UVS3010/UVS3011 | | 315 MHz |
| Venza | 2009-2015 | UVS3010/UVS3011 | | 315 MHz |
| Yaris | 2007-2015 | UVS3010/UVS3011 | | 315 MHz |
| Volkswagen | | | | |
| Beetle | 2008-2010 | UVS3010/UVS3011 | | 315 MHz |
| CC | 2009-2011 | UVS3010/UVS3011 | | 315 MHz |
| CC | 2011-2014 | UVS4010/UVS4011 | RDE013V21 | 433 MHz |
| Eos | 2007-2015 | UVS3010/UVS3011 | | 315 MHz |
| Golf | 2006-2011 | UVS3010/UVS3011 | | 315 MHz |
| GTI | 2006-2012 | UVS3010/UVS3011 | | 315 MHz |
| Jetta | 2006-2010 | UVS3010/UVS3011 | | 315 MHz |
| Passat | 2006-2010 | UVS3010/UVS3011 | | 315 MHz |
| Phaeton | 2002-2007 | | RDE001V21 | 433 MHz |
| Phaeton | 2002-2006 | | RDE004V21 | 315 MHz |
| Phaeton | 2007 | UVS2000 | RDE011V21 | 433 MHz |
| R32 | 2008 | UVS3010/UVS3011 | | 315 MHz |
| Rabbit | 2006-2009 | UVS3010/UVS3011 | | 315 MHz |
| Routan | 2009-2010 | UVS4010/UVS4011 | | 433 MHz |
| Routan | 2012 | UVS4010/UVS4011 | | 433 MHz |
| Tiguan | 2009-2011 | UVS3010/UVS3011 | | 315 MHz |
| Touareg | 2014 | | RDE022V21 | 315 MHz |
| Touareg | 2002-2007 | | RDE005V21 | 433 MHz |
| Touareg | 2007-2014 | UVS2000 | RDE011V21 | 433 MHz |
| Volvo | | | | |
| C30 | 2007-2013 | UVS4010/UVS4011 | | 433 MHz |
| C70 | 2006-2013 | UVS4010/UVS4011 | | 433 MHz |
| S40 | 2004-2011 | UVS4010/UVS4011 | | 433 MHz |
| S60 | 2004-2009 | UVS3010/UVS3011 | | 315 MHz |
| S60 | 2011-2016 | UVS4010/UVS4011 | | 433 MHz |
| S80 | 2004-2006 | UVS3010/UVS3011 | | 315 MHz |
| S80 | 2007-2015 | UVS4010/UVS4011 | | 433 MHz |
| V50 | 2005-2011 | UVS4010/UVS4011 | | 433 MHz |
| V60 | 2015 | UVS4010/UVS4011 | | 433 MHz |
| V70 | 2004-2007 | UVS3010/UVS3011 | | 315 MHz |
| V70 | 2008-2010 | UVS4010/UVS4011 | | 433 MHz |
| XC60 | 2010-2015 | UVS4010/UVS4011 | | 433 MHz |
| XC70 | 2004-2008 | UVS3010/UVS3011 | | 315 MHz |
| XC70 | 2008-2015 | UVS4010/UVS4011 | | 433 MHz |
| XC90 | 2004-2014 | UVS3010/UVS3011 | | 315 MHz |

| Make/Model | Year | IntelliSens Universal | OE Replacement | Frequency |
|------------|-----------|-----------------------|-------------------------|-----------|
| VPG | | | | |
| MV-1 | 2011-2013 | UVS3010/UVS3011 | RDE016V21/ RDE023V41 | 315 MHz |

OE Replacement Sensors

Huf develops and produces tire pressure monitoring systems for renowned car and truck manufacturers around the world.

Huf provides the market with original replacement sensors in OE quality for all systems supplied to vehicle manufacturers. The replacement tire sensors can be installed directly without configuration, they are automatically detected, identified and registered by the vehicle system. No further steps are necessary.

*Note: Huf OE Replacement Sensors come in a sleep mode to prolong the life of the battery. Sensor must be put under min 23psi pressure for 4 minutes before any readings can be retrieved from the sensor.

PART NO. RDE001V21



Myers #23700

| | |
|-------------|---|
| Frequency | 433 MHz |
| Application | Alfa Romeo, Audi, Bentley, Ferrari, Maybach, Maserati, Mercedes-Benz, Porsche, Volkswagen |

PART NO. RDE002V21



Myers #23701

| | |
|-------------|---------|
| Frequency | 433 MHz |
| Application | BMW |

PART NO. RDE003V21



Myers #23702

| | |
|-------------|-----------------|
| Frequency | 433 MHz |
| Application | BMW, Land Rover |

OE Replacement Sensors (Cont.)

PART NO. RDE004V21



Myers #23703

| | |
|-------------|--|
| Frequency | 315 MHz |
| Application | Audi, BMW, Maybach, Mercedes-Benz, Porsche, Volkswagen |

PART NO. RDE005V21



Myers #23704

| | |
|-------------|------------------------------|
| Frequency | 433 MHz |
| Application | Ferrari, Porsche, Volkswagen |

PART NO. RDE008V21



Myers #23705

| | |
|-------------|-----------|
| Frequency | 433 MHz |
| Application | BMW, Mini |

PART NO. RDE009



Myers #23706

| | |
|-------------|--------------------------------|
| Frequency | 433 MHz |
| Application | ITEC, Nova Bus, Prevost, Volvo |

PART NO. RDE011V21



Myers #23707

| | |
|-------------|--|
| Frequency | 433 MHz |
| Application | Audi, Bentley, Ferrari, Lamborghini, Maserati, Porsche, Volkswagen |

OE Replacement Sensors (Cont.)

PART NO. RDE012V21



Myers #23708

| | |
|-------------|------------------------|
| Frequency | 433 MHz |
| Application | BMW, Mini, Rolls-Royce |

PART NO. RDE013V21



Myers #23709

| | |
|-------------|------------|
| Frequency | 433 MHz |
| Application | Volkswagen |

PART NO. RDE014V21



Myers #23710

| | |
|-------------|-------------------------------|
| Frequency | 315 MHz |
| Application | Ford, Lincoln, Mazda, Mercury |

PART NO. RDE015V21



Myers #23711

| | |
|-------------|---------------|
| Frequency | 315 MHz |
| Application | Ford, Lincoln |

PART NO. RDE016V21



Myers #23712

| | |
|-------------|------------------------------------|
| Frequency | 315 MHz |
| Application | Ford, Lincoln, Mazda, Mercury, VPG |

OE Replacement Sensors (Cont.)

PART NO. RDE017V21



Myers #23713

| | |
|-------------|-----------|
| Frequency | 433 MHz |
| Application | BMW, Mini |

PART NO. RDE018V21



Myers #23714

| | |
|-------------|---------------------|
| Frequency | 433 MHz |
| Application | Porsche, Volkswagen |

PART NO. RDE019V21



Myers #23715

| | |
|-------------|--------------|
| Frequency | 315 MHz |
| Application | Hyundai, KIA |

PART NO. RDE020V21



Myers #23716

| | |
|-------------|--------------|
| Frequency | 315 MHz |
| Application | Hyundai, KIA |

OE Replacement Sensors (Cont.)

PART NO. RDE021



Myers #23717

| | |
|-------------|---------------------|
| Frequency | 433 MHz |
| Application | Mercedes-Benz Truck |

PART NO. RDE022V21



Myers #23718

| | |
|-------------|---------------------------|
| Frequency | 315 MHz |
| Application | Audi, Porsche, Volkswagen |

PART NO. RDE023V41 (rubber valve)



Myers #23736

| | |
|-------------|------------------------------------|
| Frequency | 315 MHz |
| Application | Ford, Lincoln, Mazda, Mercury, VPG |

PART NO. RDE027V21



Myers #23737

| | |
|-------------|-----------|
| Frequency | 433 MHz |
| Application | BMW, Mini |

Huf IntelliSens Universal Sensors

In addition to the OE sensors, Huf has specifically developed a universal sensor of equivalent quality which contains the full OE functionality. IntelliSens universal sensors are available in just a few versions that replace nearly all common OE TPMS sensors. The reduced variations allows for lower inventory requirements and makes it easier to have the sensor you need, when you need it.

Protocols are already installed on the IntelliSens sensor so setting the sensor is easy and fast taking only seconds to set using a TPMS diagnostic tool. With Huf's valve and sensor configuration, you can install the sensors on both OE and Aftermarket rims without a problem, without the issue of working under the rim.

*Note: Valves must be tightened using a torque wrench to 35in.lbs. (4Nm). IntelliSens must be configured using a TPMS tool or it will not register with the vehicle when doing the relearn process.

PART NO. UVS2000



Myers #23720

| | |
|-------------|--|
| Frequency | 433 MHz |
| Application | Audi, Bentley, BMW, Ferrari, Lamborghini, Maserati, Porsche, Rolls-Royce, Volkswagen |

PART NO. UVS3010



Myers #23738

| | |
|-------------|---|
| Frequency | 315 MHz |
| Application | Acura, Audi, Buick, Cadillac, Chevrolet, Chrysler, Dodge, Ford, Freightliner, GMC, Honda, Hummer, Hyundai, Infiniti, Isuzu, Jaguar, Jeep, Kia, Land Rover, Lexus, Lincoln, Mazda, Mercedes-Benz, Mercury, Mitsubishi, Nissan, Pontiac, Saab, Saturn, Scion, Subaru, Suzuki, Toyota, Volkswagen, Volvo |

PART NO. UVS3011



Myers #23722

| | |
|-------------|---|
| Frequency | 315 MHz |
| Application | Acura, Audi, Buick, Cadillac, Chevrolet, Chrysler, Dodge, Ford, Freightliner, GMC, Honda, Hummer, Hyundai, Infiniti, Isuzu, Jaguar, Jeep, Kia, Land Rover, Lexus, Lincoln, Mazda, Mercedes-Benz, Mercury, Mitsubishi, Nissan, Pontiac, Saab, Saturn, Scion, Subaru, Suzuki, Toyota, Volkswagen, Volvo |

Huf IntelliSens Universal Sensors (cont.)

PART NO. UVS4010

Myers #23719



| | |
|-------------|--|
| Frequency | 433 MHz |
| Application | BMW, Buick, Cadillac, Chevrolet, Chrysler, Dodge, Fiat, Freightliner, Hyundai, Infiniti, Isuzu Jeep, Kia, Lotus, Mercedes-Benz, Mini, Mitsubishi, Nissan, Porsche, Ram, Rolls-Royce, Saab, Saturn, Smart, SRT, Volkswagen, Volvo |

PART NO. UVS4011

Myers #23739



| | |
|-------------|--|
| Frequency | 433 MHz |
| Application | BMW, Buick, Cadillac, Chevrolet, Chrysler, Dodge, Fiat, Freightliner, Hyundai, Infiniti, Isuzu Jeep, Kia, Lotus, Mercedes-Benz, Mini, Mitsubishi, Nissan, Porsche, Ram, Rolls-Royce, Saab, Saturn, Smart, SRT, Volkswagen, Volvo |

Valves

PART NO. RDV021



Myers #23731

| | |
|--------------|--------|
| Valve Length | 43 mm |
| Color | Silver |
| Generation | 2 |

PART NO. RDV027



Myers #23741

| | |
|--------------|----------|
| Valve Length | 43 mm |
| Color | Titanium |
| Generation | 2 |

PART NO. RDV022



Myers #23732

| | |
|--------------|--------|
| Valve Length | 48 mm |
| Color | Silver |
| Generation | 2 |

PART NO. RDV023



Myers #23733

| | |
|--------------|--------|
| Valve Length | 49 mm |
| Color | Silver |
| Generation | 2 |

PART NO. RDV024



Myers #23734

| | |
|--------------|--------|
| Valve Length | 51 mm |
| Color | Silver |
| Generation | 2 |

PART NO. RDV025



Myers #23735

| | |
|--------------|--------|
| Valve Length | 56 mm |
| Color | Silver |
| Generation | 2 |

PART NO. RDV026



Myers #23740

| | |
|--------------|-------|
| Valve Length | 43 mm |
| Color | Black |
| Generation | 2 |

OE Interchange

| OE Number | IntelliSens | OE Replacement |
|----------------|-------------|-----------------|
| 185189 | RDE001V21 | |
| 239298 | RDE011V21 | UVS2000 |
| 99760602101 | RDE001V21 | |
| 52933-B2100 | | UVS4010/UVS4011 |
| 000 822 3306 | RDE001V21 | |
| 000 822 3406 | RDE004V21 | |
| 000 905 0030 | | UVS4010/UVS4011 |
| 000 905 4100 | | UVS4010/UVS4011 |
| 000 905 7200 | | UVS4010/UVS4011 |
| 002 540 6817 | RDE004V21 | UVS3010/UVS3011 |
| 002 540 7917 | RDE004V21 | UVS3010/UVS3011 |
| 002 540 9417 | | UVS3010/UVS3011 |
| 003 540 0217 | | UVS4010/UVS4011 |
| 005 542 2318 | RDE001V21 | |
| 005 542 2418 | RDE004V21 | |
| 12768826-BLACK | | UVS3010/UVS3011 |
| 12768826-GREY | | UVS3010/UVS3011 |
| 13172567 | | UVS4010/UVS4011 |
| 13227143 | | UVS4010/UVS4011 |
| 13581558 | | UVS3010/UVS3011 |
| 13581559 | | UVS3010/UVS3011 |
| 13586335 | | UVS3010/UVS3011 |
| 13589597 | | UVS3010/UVS3011 |
| 15114379 | | UVS3010/UVS3011 |
| 15122618 | | UVS3010/UVS3011 |
| 15136883 | | UVS3010/UVS3011 |
| 15268606 | | UVS3010/UVS3011 |
| 15921013 | | UVS3010/UVS3011 |
| 15922396 | | UVS3010/UVS3011 |
| 1K0-907-253A | | UVS3010/UVS3011 |
| 1K0-907-253D | | UVS3010/UVS3011 |
| 1K0-907-255A | | UVS3010/UVS3011 |
| 1K0-907-255C | | UVS3010/UVS3011 |
| 2000680 | RDE011V21 | UVS2000 |
| 20922900 | | UVS3010/UVS3011 |
| 20923680 | | UVS3010/UVS3011 |
| 20964159 | | UVS3010/UVS3011 |
| 224548 | RDE004V21 | |
| 224549 | RDE001V21 | |
| 224551 | RDE005V21 | |
| 22853741 | | UVS3010/UVS3011 |
| 22854866 | | UVS3010/UVS3011 |
| 228887 | RDE011V21 | UVS2000 |
| 23445327 | | UVS3010/UVS3011 |
| 248887 | RDE011V21 | UVS2000 |
| 25758220 | | UVS3010/UVS3011 |
| 25774006 | | UVS3010/UVS3011 |
| 25789964 | | UVS4010/UVS4011 |
| 25920615 | | UVS3010/UVS3011 |
| 28103AG00A | | UVS3010/UVS3011 |
| 28103AG01B | | UVS3010/UVS3011 |
| 28103AG01C | | UVS3010/UVS3011 |
| 28103AJ00A | | UVS3010/UVS3011 |
| 28103CA000 | | UVS3010/UVS3011 |
| 282189 | RDE011V21 | UVS2000 |
| 30681555 | | UVS4010/UVS4011 |
| 30748991 | | UVS3010/UVS3011 |
| 31200923 | | UVS3010/UVS3011 |
| 31280297 | | UVS4010/UVS4011 |
| 31302096 | | UVS4010/UVS4011 |
| 31341893 | | UVS4010/UVS4011 |
| 36106790054 | RDE012V21 | UVS4010/UVS4011 |
| 36106798872 | RDE017V21 | UVS4010/UVS4011 |
| 36106856209 | RDE027V21 | UVS4010/UVS4011 |
| 36106856227 | RDE012V21 | UVS4010/UVS4011 |
| 36118378681 | RDE004V21 | |
| 36118378682 | RDE002V21 | |
| 36146752128 | RDE003V21 | |
| 36236779490 | RDE008V21 | UVS2000 |
| 36236781847 | RDE008V21 | UVS2000 |

| OE Number | IntelliSens | OE Replacement |
|---------------|-------------|-----------------|
| 36236786896 | RDE022V21 | |
| 3AA907275 | RDE013V21 | UVS4010/UVS4011 |
| 3AA907275B | RDE013V21 | UVS4010/UVS4011 |
| 3AA907275D | RDE013V21 | UVS4010/UVS4011 |
| 40700-1A00C | | UVS3010/UVS3011 |
| 40700-1AA0A | | UVS3010/UVS3011 |
| 40700-1AA0B | | UVS3010/UVS3011 |
| 40700-1AA0C | | UVS3010/UVS3011 |
| 40700-1AA0D | | UVS3010/UVS3011 |
| 40700-1LA0C | | UVS3010/UVS3011 |
| 40700-1LA0D | | UVS3010/UVS3011 |
| 40700-1LA0E | | UVS3010/UVS3011 |
| 40700-1PA0A | | UVS3010/UVS3011 |
| 40700-3AN0A | | UVS3010/UVS3011 |
| 40700-3AN0B | | UVS3010/UVS3011 |
| 40700-3AN1A | | UVS3010/UVS3011 |
| 40700-3AN1B | | UVS3010/UVS3011 |
| 40700-3JA0A | | UVS4010/UVS4011 |
| 40700-3VU0A | | UVS4010/UVS4011 |
| 40700-4GA0A | | UVS3010/UVS3011 |
| 40700-CD001 | | UVS3010/UVS3011 |
| 40700-CK002 | | UVS3010/UVS3011 |
| 40700-JA01B | | UVS3010/UVS3011 |
| 40700-JK00A | | UVS3010/UVS3011 |
| 40700-JK00B | | UVS3010/UVS3011 |
| 40700-JK00C | | UVS3010/UVS3011 |
| 40700-JK00D | | UVS3010/UVS3011 |
| 40700-JK00E | | UVS3010/UVS3011 |
| 40700-JK01A | | UVS3010/UVS3011 |
| 40700-JK01B | | UVS3010/UVS3011 |
| 4250A030 | | UVS3010/UVS3011 |
| 4250B668 | | UVS3010/UVS3011 |
| 4250B875 | | UVS3010/UVS3011 |
| 4250B877 | | UVS3010/UVS3011 |
| 4250B975 | | UVS3010/UVS3011 |
| 4250D585 | | UVS3010/UVS3011 |
| 42607-06011 | | UVS3010/UVS3011 |
| 42607-06020 | | UVS3010/UVS3011 |
| 42607-0C020 | | UVS3010/UVS3011 |
| 42607-0C070 | | UVS3010/UVS3011 |
| 42607-0E011 | | UVS3010/UVS3011 |
| 42607-30060 | | UVS3010/UVS3011 |
| 42607-33011 | | UVS3010/UVS3011 |
| 42607-33021 | | UVS3010/UVS3011 |
| 42607-35010 | | UVS3010/UVS3011 |
| 42607-52020 | | UVS3010/UVS3011 |
| 42607-75010 | | UVS3010/UVS3011 |
| 42607-AD020 | | UVS3010/UVS3011 |
| 42753-S2A-305 | | UVS3010/UVS3011 |
| 42753-S2A-315 | | UVS3010/UVS3011 |
| 42753-SNA-A81 | | UVS3010/UVS3011 |
| 42753-SNA-A82 | | UVS3010/UVS3011 |
| 42753-SNA-A83 | | UVS3010/UVS3011 |
| 42753-SWA-306 | | UVS3010/UVS3011 |
| 42753-SWA-316 | | UVS3010/UVS3011 |
| 42753-TP6-A82 | | UVS3010/UVS3011 |
| 42753-TR0-A81 | | UVS3010/UVS3011 |
| 42753-TR3-A81 | | UVS3010/UVS3011 |
| 42753-TX6-A81 | | UVS3010/UVS3011 |
| 43130-54J20 | | UVS3010/UVS3011 |
| 43130-54J21 | | UVS3010/UVS3011 |
| 43130-54J22 | | UVS3010/UVS3011 |
| 43130-57L00 | | UVS3010/UVS3011 |
| 43130-78J00 | | UVS3010/UVS3011 |
| 43130-78J10 | | UVS3010/UVS3011 |
| 43130-85Z01 | | UVS3010/UVS3011 |
| 43211-82Z00 | | UVS3010/UVS3011 |
| 43211-82Z10 | | UVS3010/UVS3011 |
| 4D0-907-275A | RDE004V21 | |
| 4D0-907-275C | RDE001V21 | |

OE Interchange (cont.)

| OE Number | IntelliSens | OE Replacement |
|---------------|-------------|-----------------|
| 4D0-907-275D | RDE004V21 | |
| 4F0-907-275B | RDE011V21 | UVS2000 |
| 4F0-907-275C | RDE022V21 | |
| 4H23-1A-159CB | | UVS3010/UVS3011 |
| 4H23-1A-159CC | | UVS3010/UVS3011 |
| 4H23-1A-159CD | | UVS3010/UVS3011 |
| 4H23-1A-159CE | | UVS3010/UVS3011 |
| 5096808AA | | UVS4010/UVS4011 |
| 5127335AB | | UVS3010/UVS3011 |
| 52088990AC | | UVS4010/UVS4011 |
| 52933-0W100 | | UVS3010/UVS3011 |
| 52933-1F000 | | UVS3010/UVS3011 |
| 52933-2F000 | | UVS3010/UVS3011 |
| 52933-2G000 | RDE019V21 | UVS3010/UVS3011 |
| 52933-2G200 | RDE019V21 | UVS3010/UVS3011 |
| 52933-2L500 | | UVS3010/UVS3011 |
| 52933-2M000 | | UVS3010/UVS3011 |
| 52933-2M550 | | UVS3010/UVS3011 |
| 52933-2V000 | | UVS3010/UVS3011 |
| 52933-3N000 | | UVS3010/UVS3011 |
| 52933-3N100 | | UVS4010/UVS4011 |
| 52933-3V000 | | UVS3010/UVS3011 |
| 52933-3X200 | | UVS3010/UVS3011 |
| 52933-3X205 | | UVS3010/UVS3011 |
| 52933-4D000 | RDE020V21 | UVS3010/UVS3011 |
| 52933-4D200 | RDE020V21 | UVS3010/UVS3011 |
| 52933-A5000 | | UVS3010/UVS3011 |
| 56029319AA | | UVS3010/UVS3011 |
| 56029319AB | | UVS3010/UVS3011 |
| 56029319AC | | UVS3010/UVS3011 |
| 56029359AA | | UVS4010/UVS4011 |
| 56029359AB | | UVS4010/UVS4011 |
| 56029359AC | | UVS4010/UVS4011 |
| 56029398AA | | UVS4010/UVS4011 |
| 56029398AB | | UVS4010/UVS4011 |
| 56029400AB | | UVS4010/UVS4011 |
| 56029400AC | | UVS4010/UVS4011 |
| 56029400AD | | UVS4010/UVS4011 |
| 56029400AE | | UVS4010/UVS4011 |
| 56029465AA | | UVS3010/UVS3011 |
| 56029465AB | | UVS3010/UVS3011 |
| 56029465AC | | UVS3010/UVS3011 |
| 56029479AA | | UVS3010/UVS3011 |
| 56029479AB | | UVS3010/UVS3011 |
| 56053030AA | | UVS3010/UVS3011 |
| 56053030AB | | UVS3010/UVS3011 |
| 56053030AC | | UVS3010/UVS3011 |
| 56053036AA | | UVS3010/UVS3011 |
| 5L1Z-1A150-AA | | UVS3010/UVS3011 |
| 5L1Z-1A150-AB | | UVS3010/UVS3011 |
| 5Q0 907 275 | RDE018V21 | UVS4010/UVS4011 |
| 68001696AA | | UVS3010/UVS3011 |
| 68001696AB | | UVS3010/UVS3011 |
| 68001698AA | | UVS4010/UVS4011 |
| 68001698AB | | UVS4010/UVS4011 |
| 68038945AA | | UVS3010/UVS3011 |
| 68078861AA | | UVS3010/UVS3011 |
| 68157568AA | | UVS4010/UVS4011 |
| 68157568AB | | UVS4010/UVS4011 |
| 68239720AA | | UVS4010/UVS4011 |
| 68239720AB | | UVS4010/UVS4011 |
| 68239720AC | | UVS4010/UVS4011 |
| 6F2Z-1A-189A | RDE014V21 | UVS3010/UVS3011 |
| 6L2A-1A176-AE | RDE014V21 | UVS3010/UVS3011 |
| 7B0-907-253A | | UVS4010/UVS4011 |
| 7B0-907-253A | | UVS4010/UVS4011 |
| 7B0-907-253C | | UVS4010/UVS4011 |
| 7L0-907-275 | RDE005V21 | |
| 7L0-907-275B | RDE005V21 | |
| 7L1Z-1A-189A | RDE014V21 | UVS3010/UVS3011 |

| OE Number | IntelliSens | OE Replacement |
|----------------|---------------------|-----------------|
| 7PP-907-275 | RDE011V21 | UVS2000 |
| 7PP-907-275B | RDE011V21 | UVS2000 |
| 7PP-907-275D | RDE011V21 | UVS2000 |
| 7PP-907-275E | RDE022V21 | |
| 7PP-907-275F | RDE011V21 | UVS2000 |
| 7PP-907-275G | RDE022V21 | |
| 8257740060 | | UVS3010/UVS3011 |
| 8651700 | | UVS3010/UVS3011 |
| 88974915 | | UVS3010/UVS3011 |
| 8C2A-1A176-AA | RDE015V21 | UVS3010/UVS3011 |
| 8C2T-1A150-AA | RDE015V21 | UVS3010/UVS3011 |
| 8C2T-1A150-BA | RDE015V21 | UVS3010/UVS3011 |
| 8C2Z-1A189-A | RDE015V21 | UVS3010/UVS3011 |
| 92186507 | | UVS4010/UVS4011 |
| 95536166100 | RDE005V21 | |
| 95560602100 | RDE011V21 | UVS2000 |
| 95560602300 | RDE022V21 | |
| 99760602100 | RDE001V21 | |
| 99760602120 | RDE011V21 | UVS2000 |
| 99760602301 | RDE004V21 | |
| 99760602302 | RDE004V21 | |
| 99760602321 | RDE022V21 | |
| 9L3T-1A-150BD | RDE016V21/RDE023V41 | UVS3010/UVS3011 |
| 9L3T-1A-150BE | RDE016V21/RDE023V41 | UVS3010/UVS3011 |
| 9L3T-1A-180AB | RDE016V21/RDE023V41 | UVS3010/UVS3011 |
| 9L3T-1A-180AC | RDE016V21/RDE023V41 | UVS3010/UVS3011 |
| 9L3T-1A-180AD | RDE016V21/RDE023V41 | UVS3010/UVS3011 |
| 9L3T-1A-180AE | RDE016V21/RDE023V41 | UVS3010/UVS3011 |
| 9L3T-1A-180AF | RDE016V21/RDE023V41 | UVS3010/UVS3011 |
| 9L3T-1A-180BA | RDE016V21/RDE023V41 | UVS3010/UVS3011 |
| 9L3Z-1A-189A | RDE016V21/RDE023V41 | UVS3010/UVS3011 |
| AD43-360671-AA | RDE011V21 | UVS2000 |
| AD43-360671-BA | RDE022V21 | |
| BBM2-37-140 | | UVS3010/UVS3011 |
| BBM2-37-140A | | UVS3010/UVS3011 |
| BBM2-37-140B | | UVS3010/UVS3011 |
| BHA4-37-140 | | UVS3010/UVS3011 |
| C2C25519 | | UVS3010/UVS3011 |
| C2C40476 | | UVS3010/UVS3011 |
| C2C41656 | | UVS3010/UVS3011 |
| C2D21601 | | UVS3010/UVS3011 |
| C2Z15017 | | UVS3010/UVS3011 |
| CD23-360671-AA | RDE011V21 | UVS2000 |
| CD23-360671-BA | RDE022V21 | |
| CM5T-1A150-AA | RDE016V21/RDE023V41 | UVS3010/UVS3011 |
| DE8T-1A180-AA | RDE016V21/RDE023V41 | UVS3010/UVS3011 |
| DR3Z-1A189-A | | UVS3010/UVS3011 |
| F2GZ-1A-189A | | UVS3010/UVS3011 |
| GN3A-37-140B | | UVS3010/UVS3011 |
| LR003135 | | UVS3010/UVS3011 |
| LR010533 | | UVS3010/UVS3011 |
| LR010537 | | UVS3010/UVS3011 |
| LR018859 | | UVS3010/UVS3011 |
| LR018860 | | UVS3010/UVS3011 |
| LR032833 | | UVS3010/UVS3011 |
| LR032836 | | UVS3010/UVS3011 |
| LR0500461 | | UVS3010/UVS3011 |
| MN103033 | | UVS4010/UVS4011 |
| MN103081 | | UVS3010/UVS3011 |
| RQH500121 | | UVS3010/UVS3011 |
| RQH500122 | | UVS3010/UVS3011 |
| RQH500460 | | UVS3010/UVS3011 |
| RQH500461 | | UVS3010/UVS3011 |
| XR855950 | | UVS3010/UVS3011 |
| YDB000060 | RDE003V21 | |
| ZZC1-37-140 | RDE014V21 | UVS3010/UVS3011 |
| ZZDA-37-140 | RDE016V21/RDE023V41 | UVS3010/UVS3011 |
| GN3A-37-140 | | UVS3010/UVS3011 |
| GN3A-37-140A | | UVS3010/UVS3011 |
| YDB000061 | RDE003V21 | |



800-998-9897
myerstiresupply.com